

# भारतीय रेल Indian Railways

पटियाला रेलइंजन कारख़ाना, पटियाला Patiala Locomotive Works, Patiala



# LOCO TESTING & DISPATCH REPORT OF IGBT BASED 3 PHASE ELECTRIC LOCOMOTIVE

LOCO NO.: 39397

TYPE: WAP-7

RAILWAY SHED: SWR/UBL

PROPULSION SYSTEM: MEDHA

HOTEL LOAD: AAL

**DATE OF DISPATCH:** 28.08.2024

लोको निर्माण रिकार्ड



# पटियाला रेलइंजिन कारख़ाना, पटियाला Patiala Locomotive Works, Patiala

**LOCO NO. - 39397** 

**RAILWAY/SHED: SWR/UBL** 

DOD: Aug-2024

#### **INDEX**

SN	PARA	ACTIVITIES	PAGE NO.
		Testing & Commissioning (ECS)	
1.	1.0	Continuity Test of the cables	
	1.1	Continuity Test of Traction Circuit Cables	
	1.2	Continuity Test of Auxiliary Circuit Cables	1-4
	1.3	Continuity Test of Battery Circuit Cables	
	1.4	Continuity Test of Screened Control Circuit Cables	
2.	2.0	Low Tension test	
	2.1	Measurement of resistor in OHMS ( $\Omega$ )	5-6
	2.2	Check Points	5-0
	2.3	Low Tension Test Battery Circuits (without control electronics)	
3	3.0	Downloading of Software	
	3.1	Check Points	
	3.2	Download Software	7-10
	3.3	Analogue Signal Checking	
	3.4	Functional test in simulation mode	
4	4.0	Sensor test & convertor test	
	4.1	Test wiring Transformer Circuits – Polarity Test	
	4.2	Test wiring auxiliary transformer 1000V/415V-110V (pos. 67)	
	4.3	Primary Voltage Transformer	
	4.4	Minimum voltage relay (Pos. 86)	44.40
	4.5	Maximum current relay (Pos. 78)	11-16
	4.6	Test current sensors	
	4.7	Test DC Link Voltage Sensors (Pos 15.6/*)	
	4.8	Verification of Converter Protection Circuits (Hardware limits)	
	4.9	Sequence of BUR contactors	
5.	5.0	Commissioning with High Voltage	
	5.1	Check List	
	5.2	Safety test main circuit breaker	
	5.3	Auxiliary Converter Commissioning	
	5.3.1	Running test of 3 ph. auxiliary equipments	
	5.3.2	Performance of Auxiliary Converters	
	5.3.3	Performance of BURs when one BUR goes out	16-25
	5.4	Auxiliary circuit 415/110	
	5.5	Hotel Load Circuit	
	5.6	Traction Converter Commissioning	
	5.7	Test protective shutdown SR	
	5.8 5.9	Test Harmonic Filter  Test important components of the lecemetive	
6.	6.0	Test important components of the locomotive  Running Trial of the locomotive	25-26
7.	7.0	Final Check List to be verified at the time of Loco dispatch	27
8.	1-6	Annexure HLC	28-33
9.	1-10	Pneumatic Test Parameters	34-37
10.		Loco Check Sheet(LAS)	38
11.	-	Component History (LAS,ECS,ABS)	39-41
12.	-	Component History & Testing Parameter (Bogie Shop)	42-43
13	-	Warranty Conditions as per Tenders	44-46

Effective Date: Feb 2022

(Ref: WI/ECS/10)

## PATIALA LOCOMOTIVE WORKS, PATIALA

Testing & Commissioning Format For 3-Phase Locomotive fitted with IGBT based Traction Converter, Auxiliary Converter and TCN based VCU

Locomotive No.: 39397 -MEDHA

Type of Locomotive: WAP-7/WAG-9HC

Page: 1 of 27

1.0 Continuity Test of the cables

1.1 Continuity Test of Traction Circuit Cables

As per cable list given in Para 1.3 of document no. 3 EHX 410 124, check the continuity with continuity tester and megger each cable to be connected between following equipment with 1000V megger.

From	То	Continuity (OK/Not OK)	Prescribed Megger Value (min)	Measured Megger Value
Filter Cubicle	Transformer	oK	100 ΜΩ	900Ma
Filter Cubicle	Terminal Box of Harmonic Filter Resistor (Roof)	øK	100 ΜΩ	800 ma
Filter Cubicle	Earthing Choke	OK	100 ΜΩ	Boomo.
Earthing Choke	Earth Return Brushes	OK	100 ΜΩ	900m
Transformer	Power Converter 1	OK	100 ΜΩ	Sooms
Transformer	Power Converter 2	OK	100 ΜΩ	900 m
Power Converter 1	TM1, TM2, TM3	ok	100 ΜΩ	800ma
Power Converter 2	TM4, TM5, TM6	012	100 ΜΩ	Dooms
Earth	Power Converter 1	OK	100 ΜΩ	Dooms
Earth	Power Converter 2	OK	100 ΜΩ	800 MM

#### 1.2 Continuity Test of Auxiliary Circuit Cables

As per cable list given in Para 1.4 of document no. 3 EHX 410 124, check the continuity with continuity meter and megger each cable to be connected between following equipment with the help of 1000V megger.

Signature of the JE/SSE/Harness

Signature of the JE/SSE/Loco Cabling

Doc.No.F/ECS/01

(Ref: WI/ECS/10)

#### PATIALA LOCOMOTIVE WORKS, PATIALA

<u>Testing & Commissioning Format For 3-Phase Locomotive fitted with</u>
<u>IGBT based Traction Converter, Auxiliary Converter and TCN based VCU</u>

Locomotive No.: 39397

Type of Locomotive: WAP-7/WAG-9HC

Page: 2 of 27

From	То	Continuity(OK/ Not OK)	Prescribed Megger Value (min)	Measured Megger Value
Transformer	BUR1	OK	100 ΜΩ	500
Transformer	BUR2	<b>-</b>	100 MΩ	1000
Transformer	BUR3	7	100 MΩ	<u></u>
Earth	BUR1	4	100 MΩ	500
Earth	BUR2	7	100 MΩ	200
Earth	BUR3	۶	100 M $\Omega$	200
BUR1	HB1	4	100 ΜΩ	500
BUR2	HB2	ч	100 MΩ	700
HB1	HB2	4	100 ΜΩ	<u>-5W.</u>
HB1	TM Blower 1	G	100 ΜΩ	500
HB1	TM Scavenge Blower 1	c	100 MΩ	500
HB1	Oil Cooling Unit 1	47	100 M $\Omega$	500
HB1	Compressor 1	y	100 MΩ	57 90
HB1	TFP Oil Pump 1	· ·	100 MΩ	650
HB1	Converter Coolant Pump 1	9	100 ΜΩ	560
HB1	MR Blower 1	ec	$100~ extsf{M}\Omega$	400
HB1	MR Scavenge Blower 1	c	100 M $\Omega$	450
HB1	Cab1	4	$100\mathrm{M}\Omega$	250
Cab1	Cab Heater 1	4	100 ΜΩ	200
HB2	TM Blower 2	4	100 ΜΩ	500
HB2	TM Scavenge Blower 2	4	100 MΩ	Sons
HB2	Oil Cooling Unit 2	٠,	100 MΩ	1000
HB2	Compressor 2	ę	100 ΜΩ	500
HB2	TFP Oil Pump 2	4	100 ΜΩ	500
HB2	Converter Coolant Pump 2	9	100 ΜΩ	600
HB2	MR Blower 2	9	100 ΜΩ	500
HB2	MR Scavenge Blower 2	٠	100 ΜΩ	500
HB2	Cab2	~ .	100 MΩ	750
Cab2	Cab Heater 2	6.7	100 MΩ	754

Effective Date: Feb 2022

(Ref: WI/ECS/10)

### PATIALA LOCOMOTIVE WORKS, PATIALA

# <u>Testing & Commissioning Format For 3-Phase Locomotive fitted with</u> <u>IGBT based Traction Converter, Auxiliary Converter and TCN based VCU</u>

Locomotive No.: 39397

Type of Locomotive: WAP-7/WAG-9HC

Page: 3 of 27

1.3 Continuity Test of Battery Circuit Cables

Check continuity of following cables as per Para 2.3 of document no. 3 EHX 610 299

То	Condition	Continuity (OK/Not OK)
Circuit breakers 110- 2 112 1-1, 310.4-1	By opening and closing MCB 112	ok
Connector 50.X7-1	By opening and closing MCB 110	ok
Connector 50.X7-2		814
Connector 50.X7-3		ok ok
	Circuit breakers 110- 2, 112.1-1, 310.4-1 Connector 50.X7-1	Circuit breakers 110- 2, 112.1-1, 310.4-1 Connector 50.X7-1  By opening and closing MCB 112  By opening and closing MCB 110  Connector 50.X7-2

		1
Close the MCB 112, 110, 112.1, and 310.4 and	Prescribed value	Measured
measure the resistance of battery wires 2093, 2052, 2050 with respect to the loco earth.	> 0.5 MΩ	Value <u>&amp;</u> MΩ
1 hotagon 2003 & 2052	Prescribed value:	Measured
Measure the resistance between 2093 & 2052,		-
2093 & 2050, 2052 &	> 50 MΩ	Value
2050	7 33	65 MQ

Commission the indoor lighting of the locomotive as per Sheet No 7A & 7B.

#### 1.4 Continuity Test of Screened Control Circuit Cables

Check the continuity and isolation of the screen cable of the following circuits with the help of sheet no. mentioned against each as per document no. 3 EHX 610 299.

Screened control circuit cables for	Corresponding Sheet Nos.	Continuity & Isolation (OK/Not OK)
Battery voltage measurement	04B	ok
Memotel circuit of cab1 &2	10A	0K
Memotel speed sensor	10A	ok
Primary voltage detection	01A, 12A	ok
Brake controller cab-1 & 2	06F, 06G	ok

(Ref: WI/ECS/10)

# PATIALA LOCOMOTIVE WORKS, PATIALA

# Testing & Commissioning Format For 3-Phase Locomotive fitted with IGBT based Traction Converter, Auxiliary Converter and TCN based VCU

Locomotive No.: 38387

Type of Locomotive: WAP-7/WAG-9HC Page: 4 of 27

	•	
U 1 9.2	08C, 08D	ok
Master controller cab-1 &2	08E, 08F	ok
E/BE meter bogie-1 & 2	09F	ok
erminal fault indication cab-1 & 2		ok
Brake pipe pressure actual BE electric	06H	
Primary current sensors	12B, 12F	ok
Harmonic filter current sensors	12B, 12F	ok
Auxiliary current sensors	12B, 12F	OK
Oil circuit transformer bogie 1	12E, 12I	eK.
	12C, 12G	%K
Magnetization current  Traction motor speed sensors (2 nos.)	12D	ok
and temperature sensors (1 (10.) of the -		
Traction motor speed sensors (2005)	12D	ok
and temperature sensors (1 no.) of five-2	12D	
Treation motor speed sensors (2nos)	120	ok
and temperature sensors (1 no.) of TM-3	12H	ok
Traction motor speed sensors (2 nos.) and temperature sensors (1 no.) of TM-4		
Traction motor speed sensors (2005)	12H	οk
and temperature sensors (1 no.) of TWI-3		
Traction motor speed sensors (2nos)	12H	o k
and temperature sensors (1 no.) of 1101-6		
Train Bus cab 1 & 2	13A	ok
(Wire U13A& U13B to earthing resistance=		OK .
10KΩ± ± 10%)		
UIC line	13B	ð.K
Connection FLG1-Box TB	13A	ok .

#### (Ref: WI/ECS/10)

# PATIALA LOCOMOTIVE WORKS, PATIALA

## Testing & Commissioning Format For 3-Phase Locomotive fitted with IGBT based Traction Converter, Auxiliary Converter and TCN based VCU

Locomotive No.: 38387

Type of Locomotive: WAP-7/WAG-9HC Page: 5 of 27

2.0 Low Tension test

Measure the resistances of the load resistors for primary voltage transformer, load resistors for primary current transformer and Resistor harmonic filter as per Para 3.2 of the document no. 3 EHX 610 279.

	Prescribed value	Measured value
lame of the resistor	3.9K <b>Ω</b> ± 10%	3.8100
oad resistor for primary voltage ransformer (Pos. 74.2).	·	152
Resister to maximum current relay.	1Ω ± 10%	3.352
Load resistor for primary current	$3.3 \Omega \pm 10\%$	عواي
transformer (POS. 6.11).	WAP7	WAP7
Resistance harmonic filter (Pos 8.3). Variation	VVAF /	
allowed ± 10%		0.25
Between wire 5 & 6	0.2 Ω	0.22
Between wire 6 & 7	0.2 Ω	0.452
Between wire 5 & 7	0.4 Ω	10.0Kr
	10 k <b>Ω</b> ± 10%	988KV
For train bus, line U13A to earthing.	10 k <b>Ω</b> ± 10%	
For train bus, line U13B to earthing.  Insulation resistance of High Voltage Cable	200 MΩ	300195
from the top of the roof to the earth		·
(by1000 V megger).		0.281
Resistance measurement earth return	≤0,3 Ω	
brushes Pos. 10/1.	≤0.3 Ω	0.28-52
Resistance measurement earth return	≥0.5 12	
brushes Pos. 10/2.	≤0.3 Ω	0.281
Resistance measurement earth return	20.5 12	1.52
brushes Pos. 10/3.  Resistance measurement earth return	≤0.3 Ω	0.305
haushoc Pos 10/4		2.2×2
Earthing resistance (earth fault detection)	2.2 kΩ± 10%	2.20
Harmonic Filter –I; Pos. 8.61.	2.7 kΩ± 10%	2.750
Earthing resistance (earth fault detection)	Z./ K11 10/0	
Harmonic Filter –II; Pos 8.62.	3.9 kΩ ± 10%	3.9KM
Earthing resistance (earth fault detection)	5.5 K22 2 2070	
Aux. Converter; Pos. 90.3.  Earthing resistance (earth fault detection)	1.8 kΩ± 10%	1.8Kr
Earthing resistance (earth fault detection) 415/110V; Pos. 90.41		70. 0
Earthing resistance (earth fault detection)	390 <b>Ω</b> ± 10%	39052
control circuit; Pos. 90.7.	2.1.7.400/	NA
Earthing resistance (earth fault detection)	3.3 k <b>Ω</b> ± 10%	1
Hotel load; Pos. 37.1(III case of WAI 37.		1056
Resistance for headlight dimmer; Pos. 332.3	. 1012 2 10/0	2

Effective Date: Feb 2022

(Ref: WI/ECS/10)

# PATIALA LOCOMOTIVE WORKS, PATIALA

# Testing & Commissioning Format For 3-Phase Locomotive fitted with IGBT based Traction Converter, Auxiliary Converter and TCN based VCU

Locomotive No.: 39387

Type of Locomotive: WAP-7/WAG-9HC

Page: 6 of 27

Make sure that the earthing brush device don't make direct contact with the axle housing, earth connection must go by brushes.

#### 2.2 Check Points

	Remarks
Items to be checked	
Check whether all the earthing connection in roof and machine room as mentioned in sheet no. 22A is done properly or not. These earthing connections must be flexible and should be	cheebed ok
marked yellow & green  Check whether all the earthing connection between loco body and bogie is done properly or not. These cables must be flexible having correct length and cross section	cheelsed of

# 2.3 Low Tension Test Battery Circuits (without control electronics)

These tests are done with the help of the special type test loop boxes as per procedure given in Para 3.6 of the document no. 3 FHX 610 279

Para 3.6 of the document no. 3 EHX 61  Name of the test	Schematic used.	Remarks
Test 24v supply	Sheet 04F and other linked sheets Sheet 04F & sheets of group 09	Checked ok Fan supply to be checked.
Test 46V supply	Sheets of Group 08.	ok ok
Test traction control  Test power supply bus stations.	Sheets of Group 09.	Fan supply to be checked ok
Test control main apparatus	Sheets of Group 05.	OK.
Test earth fault detection battery circuit by making artificial earth fault	Sheet 04C	ok
to test the earth fault detection  Test control Pneumatic devices	Sheets of Group 06	ok
Test-lighting control	Sheets of Group 07	6K
Pretest speedometer	Sheets of Group 10	ök
Pretest vigilance control and fire	Sheets of Group 11	ok
Power supply train bus	Sheets of Group 13	ok .

#### (Ref: WI/ECS/10)

# PATIALA LOCOMOTIVE WORKS, PATIALA

# Testing & Commissioning Format For 3-Phase Locomotive fitted with IGBT based Traction Converter, Auxiliary Converter and TCN based VCU

Locomotive No.: 39397

Type of Locomotive: WAP-7/WAG-9HC

Page: 7 of 27

Downloading of Software

3.0 Downloading of column	Yes/No
3.1 Check Points.  Check that all the cards are physically present in the bus stations and all the plugs are	Yes
connected.	Yes
all the control electronics off relay is not energized i.e. disconfident out of	Yes
Make sure that <b>control electron</b> 411.LG and loco is set up in simulation mode.  Check that battery power is on and all the MCBs (Pos. 127.*) in SB1 &SB2 are on	Yes

The software of Traction converter, Auxiliary converter and VCU should be done by commissioning engineer of the firm in presence of supervisor. Correct software version of the

propulsion equipment to be ensured and noted:	1.93
Traction converter-1 software version:	1.07
Traction converter-2 software version:	1.04
Auxiliary converter-1 software version:	1.04
Auxiliary converter-2 software version:	1,04
Auxiliary converter-3 software version:	30
Vehicle control unit -1 software version:	3.0
Vehicle control unit -2 software version:	

3.3 Analogue Signal Checking

Check for the following analogue signals with the help of diagnostic tool connected with loco

Description	analogue signals with the help of diag Signal name	Prescribed value	Measured Value
Brake pipe pressure	FLG2;0101XPrAutoBkLn .	100% (= 5 Kg/cm2)	-ok
Actual BE electric	FLG2; AMSB_0201- Wpn BEdem	100% (= 10V)	效
TE/BE at 'o' position	FLG1; AMSB_0101- Xang Trans	Between 9% and 11 %	104,
from both cab	FLG2; AMSB_0101- Xang Trans FLG1; AMSB_0101- Xang Trans	Between 99 % and 101 %	100.1
TE/BE at 'TE maximal' position from both cab	FLG2; AMSB_0101- Xang Trans		
TE/BE at 'TE minimal' position from both cal		Between 20 % and 25 %	25),

# PATIALA LOCOMOTIVE WORKS, PATIALA

# Testing & Commissioning Format For 3-Phase Locomotive fitted with IGBT based Traction Converter, Auxiliary Converter and TCN based VCU

Locomotive No.: 39397

Type of Locomotive: WAP-7/WAG-9HC

Page: 8 of 27

			· ·
E/BE at 'BE maximal' position from both cab	FLG1; AMSB_0101- XangTrans FLG2; AMSB_0101-	Between 99% and 101%	1001,
TE/BE at 'BE Minimal' position from both cab	XangTrans FLG1; AMSB_0101- XangTrans FLG2; AMSB_0101-	Between 20% and 25%	257,
TE/BE at '1/3' position in TE and BE mode in both cab.	XangTrans HBB1; AMS_0101- LT/BDEM>1/3 HBB2; AMS_0101- LT/BDEM>1/3	Between 42 and 44%	441
TE/BE at '1/3' position in TE and BE mode in both cab.		Between 72 and 74%	741-
Both temperature sensor of TM1	SLG1; AMSB_0106- XAtmp1Mot	Between 10% to 11.7% depending upon ambient temperature $0^{\circ}$ C to $40^{\circ}$ C	1400
Both temperature sensor of TM2	SLG1; AMSB_0106- Xatmp2Mot	Between 10% to 11.7% depending upon ambient temperature 0°C to 40°C	
Both temperature sensor of TM3	SLG1; AMSB_0106- Xatmp3Mot	<u> </u>	13.5
Both temperature sensor of TM4	SLG2; AMSB_0106- XAtmp1Mot		5 7 7
Both temperature sensor of TM5	SLG2; AMSB_0106 Xatmp2Mot		0 79
Both temperature sensor of TM6	SLG2; AMSB_0106- Xatmp3Mot	Between 10% to 11.7% depending upon ambient temperature 0°C to 40°C	13°C

(Ref: WI/ECS/10)

# PATIALA LOCOMOTIVE WORKS, PATIALA

# Testing & Commissioning Format For 3-Phase Locomotive fitted with IGBT based Traction Converter, Auxiliary Converter and TCN based VCU

Locomotive No.: 38387

Type of Locomotive: WAP-7/WAG-9HC Page: 9 of 27

#### Functional test in simulation mode 3.4

Conduct the following functional tests in simulation mode as per Para 5.5 of document no.3EHX 610 281. through the Diagnostic tool/laptop:

est Function	Result desired in sequence	Result obtained
mergency shutdown through mergency stop switch 244	VCB must open. Panto must lower.	cheebael ok
Shut Down through cab activation switch to OFF position	VCB must open. Panto must lower.	checheel of
Converter and filter contactor operation with both Power Converters during Start Up.	FB contactor 8.41 is closed.  By moving reverser handle:  Converter pre-charging contactor 12.3 must close after few seconds.  Converter contactor 12.4 must close.  Converter re-charging contactor 12.3 must opens.  By increasing TE/BE throttle:  FB contactor 8.41 must open.  FB contactor 8.2 must close.  FB contactor 8.1 must close.	cheebed of
Converter and filter contact operation with both Pow Converters during Shut Down.	or Bring TE/BE to O.	

# PATIALA LOCOMOTIVE WORKS, PATIALA

# Testing & Commissioning Format For 3-Phase Locomotive fitted with IGBT based Traction Converter, Auxiliary Converter and TCN based VCU

Locomotive No.: 39397

Type of Locomotive: WAP-7/WAG-9HC Page: 10 of 27

(Ref: WI/ECS/10)

solating any bogie	After raising panto, closing VCB, and	cheebeed ok
	to earth, create earth fault positive potential.  • message for earth fault	checked ok
Test fire system. Create a smoke in the machine room near the FDU. Watch for activation of alarm.	<ul> <li>When smoke sensor-1 gets activated then</li> <li>Alarm triggers and fault message priority 2 appears on screen.</li> <li>When both smoke sensor 1+2 gets activated then</li> <li>A fault message priority 1 appears on screen and lamp LSF1 glow.</li> <li>Start/Running interlock occurs and TE/BE becomes to 0.</li> </ul>	cheebed ox
Time, date & loco number	Ensure correct date time and Loco number	Cheebed of

(Ref: WI/ECS/10) फ़ुक्ट . जुप **प** 

# PATIALA LOCOMOTIVE WORKS, PATIALA

Testing & Commissioning Format For 3-Phase Locomotive fitted with IGBT based Traction Converter, Auxiliary Converter and TCN based VCU

Locomotive No.: 38397

Type of Locomotive: WAP-7/WAG-9HC

Page: 11 of 27

### Sensor Test and Converter Test

4.1 Test wiring main Transformer Circuits

Apply  $198V_p/140V_{RMS}$  to the primary winding of the transformer (at 1u; wire no. 2 at surge arrestor and at 1v; wire no. 100 at earthing choke). Measure the output voltage and compare

the phase of the following of the transformers.

he phase of the Dutput Winding nos.	following of the transformers.  Description of winding.	Prescribed Output Voltage & Polarity with input supply.	I I I I COD ON I TO	Measured polarity
2U <sub>1</sub> & 2V <sub>1</sub>	For line converter bogie 1 between cable 801A- 804A	10.05V <sub>p</sub> and same polarity	10-0470	OK-
2U <sub>4</sub> & 2V <sub>4</sub>	For line converter bogie 1 between cable 811A-814A	10.05V <sub>p</sub> and same polarity	10.0518	QC.
2U <sub>2</sub> & 2V <sub>2</sub>	For line converter bogie 2 between cable 801B- 804B	10.05V <sub>p</sub> and same polarity	10.041	or.
2U <sub>3</sub> & 2V <sub>3</sub>	For line converter bogie 2 between cable 811B- 814B	10.05V <sub>p</sub> and same polarity	10.041	en.
2U <sub>B</sub> & 2V <sub>B</sub>	For aux. converter 1 between cable 1103- 1117 (in HB1) For Aux converter 2 between cable 1103- 1117 (in HB2)	7.9V <sub>p</sub> , 5.6V <sub>RMS</sub> and same polarity.	7.8 VP (S)	OK.
2U <sub>F</sub> & 2V <sub>F</sub>	For harmonic filter between cable 4-12 (in FB)	9.12V <sub>p</sub> , 6.45V <sub>RMS</sub> and same polarity.	9.10Vl 6.44URPS	en

# 4.2 Test wiring auxiliary transformer 1000V/415V-110V (pos. 67)

Apply  $141V_p$  /  $100V_{RMS}$  to input of the auxiliary transformer at cable no 1203 –1117 and measure the output at

Description of wire no.	Prescribed Output Voltage & Polarity with input supply.	Measured output	Measured polarity
Cable no. 1218 - 1200	==== to 14 EV and apposite polarity	586 Vl 415 Vems)	· OX
Cable no. 1218 – 6500		<del>                                     </del>	OK.

Effective Date: Feb 2022

#### PATIALA LOCOMOTIVE WORKS, PATIALA

Testing & Commissioning Format For 3-Phase Locomotive fitted with IGBT based Traction Converter, Auxiliary Converter and TCN based VCU

Locomotive No.: 38387

Type of Locomotive: WAP-7/WAG-9HC

Page: 12 of 27

(Ref: WI/ECS/10)

#### Primary Voltage Transformer 4.3

Apply  $250V_{eff}/350V_p$  by variac to roof wire 1 and any wire 0 and measure the magnitude and polarity of the output of the primary voltage transformer for both bogies as per the procedure specified and suggested by the traction converter manufacturer. Primary voltage measurement converters (Pos. 224.1/\*) & catenary voltmeter (Pos. 74/\*)

This test is to be done for each converter.

Activate cab in driving mode and supply  $200V_{RMS}$  through variac to wire no 1501 and 1502. Monitor the following parameters through Diagnostic tool and in catenary voltmeter.

Signal name	Prescribed value in catenary voltmeter	Prescribed value in Micview	Monitored value in catenary voltmeter	Monitored value in SR diagnostic tool
SLG1 G 87-XUPrim	25kV	250%	25KV	250/
SLG2 G 87-XUPrim	25 kV	250%	25 KV	250-/

Decrease the supply voltage below 140  $V_{\text{RMS}}$ . VCB must open at this voltage. In this case the readings in Diagnostic Tool and catenary voltmeter will be as follows.

Signal name	Prescribed value in catenary voltmeter	Prescribed value in Micview	Monitored value in catenary voltmeter	Monitored value in SR diagnostic tool
SLG1 G 87-XUPrim	17kV	170%	17K1	170/
SLG2 G 87-XUPrim	17 kV	170%	17KY	170-5

Reactivate VCB to on by increasing this voltage to 175% (17.5 kV).

Increase the supply to 240  $V_{RMS}$  through variac. VCB must open at this voltage, In this case the readings in diagnostic tool and catenary voltmeter will be as follows:

Signal name	Prescribed value in catenary voltmeter	Prescribed value in Micview	Monitored value in catenary voltmeter	Monitored value in SR diagnostic tool
SLG1 G 87-XUPrim	30kV	300%	38 KV	305/-
SLG2_G 87-XUPrim	30 kV	300%	30 KV	300-/

Reactivate VCB to on by decreasing this voltage to 290% (29 kV).

Effective Date: Feb 2022

DOC.NO.P/ECS/01 (Ref: WI/ECS/10)

### PATIALA LOCOMOTIVE WORKS, PATIALA

<u>Testing & Commissioning Format For 3-Phase Locomotive fitted with</u>
<u>IGBT based Traction Converter, Auxiliary Converter and TCN based VCU</u>

Locomotive No.: 39397

Type of Locomotive: WAP-7/WAG-9HC Page: 13 of 27

#### Minimum voltage relay (Pos. 86) 4.4

Functionality test:	tod to approv 68%
Minimum voltage relay (Pos. 86) must be adjus	ted to approx 0070
Activate loco in cooling mode. Check Power supply of 48V to minimum voltage relay. Disconnect primary voltage transformer (wire no. 1511 and 1512) from load resistor (Pos. 74.2) and connect variac to wire no. 1501 and 1502. Supply 200V <sub>RMS</sub> through variac. In this case; <i>Minimum voltage relay (Pos. 86) picks up</i>	(Vés/No)
	√Yeŝ/No)
Try to activate the cab in driving mode:  Contactor 218 do not close; the control	(Jes/No)
electronics is not be working.	Mr. Mala)
Turn off the variac :	(Yes/No)
Contactor 218 closes; the control electronics is be	
working	
Test Under Voltage Protection	<u>1;</u>
<u> </u>	
Activate the cab in cooling mode; Raise panto;	(Yes/No)
Supply 200V <sub>RMS</sub> through variac to wire no. 1501	
& 1502; Close the VCB; Interrupt the supply	
voltage	•
The VCB goes off after 2 second time delay.	
Again supply 200V <sub>RMS</sub> through variac to wire no.	(Yes/No)
1501 & 1502; Decrease the supply voltage below	· ·
140V <sub>RMS</sub> ± 4V;	
Fine tune the minimum voltage relay so that VCB opens.	

4.5 Maximum current relay (Pos. 78)	·
Disconnect wire 1521 & 1522 of primary current tran &1522 (including the resistor at Pos. 6.11); Put loco in sign contact 136.3; Close VCB; supply 3.6A <sub>RMS</sub> at the communication of the communication	mulation for driving mode; Open $R_3 - R_4$ open wire 1521; Tune the drum of the
VCB opens with Priority 1 fault message on display.	(Yes/No)
Keep contact $R_3$ – $R_4$ of 136.3 closed; Close VCB; Tune the /9.9 $A_p$ at the open wire 1521;	ne resistor 78.1 for the current of 7.0A <sub>RMS</sub>
VCB opens with Priority 1 fault message on display.	/Yes/No)



(Ref: WI/ECS/10)

## PATIALA LOCOMOTIVE WORKS, PATIALA

<u>Testing & Commissioning Format For 3-Phase Locomotive fitted with</u>
<u>IGBT based Traction Converter, Auxiliary Converter and TCN based VCU</u>

Locomotive No.: 39387

Type of Locomotive: WAP-7/WAG-9HC Page : 14 of 27

4.6 Test current sensors Name of the sensor	Description of the test	Prescribed value	Set/Measured value
Primary return current sensor (Test-1,Pos.6.2/1 & 6.2/2)	Activate cab in driving mode supply 10A. Measure the current through diagnostic tool or measuring print.	(Variation allowed is ± 10%)	
Deliver our our out	Supply 90mA <sub>DC</sub> to the test winding of sensor through connector 415.AA/1or 2 pin no. 7(+) & 8(-)		
Primary return current sensor (Test-2, Pos.6.2/1 & 6.2/2)	Supply 297mA <sub>DC</sub> to the test winding of sensor through connector 415.AA/101 2 pin no. 7(+) & 8(-)		2-99 mg
Auxiliary winding current sensor (Pos. 42.3/1 & 42.3/2)	Supply 90mA <sub>DC</sub> to the test winding of sensor through connector 415.AC/10 2 pin no. 7(+) & 8(-) Supply 333mA <sub>DC</sub> to the test winding of sensor through connector 415.AC/1 or 2 pin no. 7(+) & 8(-)	r]	339ma
Harmonic filter current sensors (Pos.8.5/1 &8.5/2)	Supply 90mA <sub>DC</sub> to the test winding o sensor through connector 415.AE/1c 2 pin no. 7(+) & 8(-)	or	
	Supply 342mA <sub>DC</sub> to the test winding o sensor through connector 415.AE/10 2 pin no. 7(+) & 8(-)	or	348mp
Hotel load current sensors (Pos. 33/1 &	Switch on hotel load. Supply 90mA <sub>Di</sub> to the test winding of sensor through connector 415.AG/1or 2 pin no. 7(+) 8(-)	ו ו   י	
33/2)	Supply 1242mA <sub>DC</sub> to the test windin of sensor through connector 415.AG/1or 2 pin no. 7(+) & 8(-)	g	1250 mis

DOC:140'1 \FOO\A (Ref: WI/ECS/10)

#### PATIALA LOCOMOTIVE WORKS, PATIALA

Testing & Commissioning Format For 3-Phase Locomotive fitted with IGBT based Traction Converter, Auxiliary Converter and TCN based VCU

Locomotive No.: 39397

Type of Locomotive: WAP-7/WAG-9HC

Page: 15 of 27

4.7 Test DC Link Voltage Sensors (Pos 15.6/\*)

This test is to be done by the commissioning engineer of the firm if required.

### 4.8 Verification of Converter Protection Circuits (Hardware limits) -

This test is to be done as per para 6.17 of the document no. 3EHX 610 282 for both the converters.

Protection circuits	Limit on which shutdown should take place	Measured limit
Current sensors (Pos 18.2/1, 18.2/2, 18.2/3, 18.4/4, 18.5/1, 18.5/2, 18.5/3) for Power Converter 1	Increase the current quickly in the test winding of the current sensors, VCB will off at 2.52A with priority 1 fault for each sensor.	For 18.2/1= For 18.2/2= For 18.2/3= For 18.4/4= For 18.5/1= For 18.5/2= For 18.5/3=
Current sensors (Pos 18.2/1, 18.2/2, 18.2/3, 18.4/4, 18.5/1, 18.5/2, 18.5/3) for Power Converter 2	Increase the current quickly in the test winding of the current sensors, VCB will off at 2.52A with priority 1 fault for each sensor.	For 18.2/1= For 8.2/2= For 18.2/3= For 18.4/4= For 18.5/1= For 18.5/2= For 18.5/3=
Fibre optic failure in Power Converter1	Remove one of the orange fibre optic plugs on traction converter. VCB should trip	OK
Fibre optic failure In Power Converter2	Remove one of the orange fibre optic plugs on traction converter. VCB should trip	O.

#### 4.9 Sequence of BUR contactors

The sequence of operation of BUR contactors for 'ALL BUR OK' BUR 1 out BUR 2 out and BUR 3 out condition has to be verified by putting the Loco in driving mode (VCB should not be closed) and isolating the BURs one by one. In these condition following will be the contactor sequence.

_		į.							
Status	52/1	52/2	52/3	52/4	52/5	52.4/1	52.4/2	52.5/1	52.5/2
AI BUR OK	Close	Open	Close	Open	Close	Open	Close	Close	Open
BUR1 off	Close	Open	Close	Close	Open	Close	Open	Open	Close
BUR2 off	Open	Open	Close	Close	Close	Close	Open	Open	Close
BUR3 off	Open	Close	Open	Close	Close	Close	Open	Open	Close

#### PATIALA LOCOMOTIVE WORKS, PATIALA

<u>Testing & Commissioning Format For 3-Phase Locomotive fitted with</u>
<u>IGBT based Traction Converter, Auxiliary Converter and TCN based VCU</u>

Locomotive No.: 39357

Type of Locomotive: WAP-7/WAG-9HC

Page: 16 of 27

(Ref: WI/ECS/10)

Monitored contactor sequence

T	E2/1	52/2	52/3	52/4	52/5	52.4/1	52.4/2	52.5/1	52.5/2
Status	52/1	<del></del>	<del> </del> _	<del> </del>	clos	den	Clop	close	Day
AI BUR OK	log .	open	clos	open		<del></del>	open	obco	close
BUR1 off	Class.	open	clos	108	<del>  V </del>	close	Oben	1 7 /	class
BUR2 off	open	open	class	clos	Class.	Les		<del></del>	
BUR3 off	oben	clise	open	dos	رانگان	close	open	oper	close

#### 5.0 Commissioning with High Voltage

#### 5.1 Check List

Items to be checked	Yes/No
Fibre optic cables connected correctly.	Yes
No rubbish in machine room, on the roof, under the loco.	Yes
All the electronic Sub-D and connectors connected	Yes
All the MCBs of the HB1 & HB2 open.	Yes
All the three fuses 40/* of the auxiliary converters	Yes
The fuse of the 415/110V auxiliary circuit (in HB1) open.	Yes
Roof to roof earthing and roof to cab earthing done	Yes
Fixing, connection and earthing in the surge arrestor done correctly.	Yes
Connection in all the traction motors done correctly.	Yes
All the bogie body connection and earthing connection done correctly.	Yes
Pulse generator (Pos. 94.1) connection done correctly.	Yes
All the oil cocks of the gate valve of the transformer in open condition.	yes
All covers on Aux & Power converters, Filter block, HB1, HB2 fitted	Yes
KABA key interlocking system.	Yes

#### 5.2 Safety test main circuit breaker

Prepare to switch off the catenary supply during the first charging of the locomotive in case of any unexpected behavior of the electrical component of the loco. Charge the loco for the first time by closing BLDJ switch. The VCB will trip after certain time as no oil/coolant pumps are running yet.

Perform the following safety test of main circuit breaker through both the cabs of the locomotive.

Effective Date: Feb 2022

DOC:NO.F/ECS/01 (Ref: WI/ECS/10)

#### PATIALA LOCOMOTIVE WORKS, PATIALA

<u>Testing & Commissioning Format For 3-Phase Locomotive fitted with</u>
<u>IGBT based Traction Converter, Auxiliary Converter and TCN based VCU</u>

Locomotive No.: 39397

Type of Locomotive: WAP-7/WAG-9HC Page : 17 of 27

Name of the test	Description of the test	Expected result	Monitored result
Emergency stop in cooling mode	Raise panto in cooling mode. Put the brake controller into RUN position. Close the VCB. Push emergency stop button 244.	VCB must open. Panto must lower. Emergency brake will be applied.	cheahed ok
Emergency stop in driving mode	Raise panto in driving mode in. Put the brake controller into RUN position. Close the VCB. Push emergency stop button 244.	VCB must open. Panto must lower. Emergency brake will be applied.	checked ok
Under voltage protection in cooling mode	Raise panto in cooling mode. Close the VCB. Switch off the supply of catenary by isolator	VCB must open.	Checked ok
Under voltage protection in driving mode	Raise panto in driving mode. Close the VCB. Switch off the supply of catenary by isolator	VCB must open with diagnostic message that catenary voltage out of limits	cheebed ok
Shut down in cooling mode.	Raise panto in cooling mode. Close the VCB. Bring the BL- key in O position.	VCB must open. Panto must lower.	checked ok
Shutdown in driving mode	Raise panto in driving mode. Close the VCB. Bring the BL-key in O position.	VCB must open. Panto must lower.	checked ok
Interlocking pantograph- VCB in cooling mode	Raise panto in cooling mode. Close the VCB. Lower the pantograph by ZPT	VCB must open.	eneched ox
Interlocking pantograph-VCB in driving mode	Raise panto in driving mode. Close the VCB. Lower the pantograph by ZPT	VCB must open.	cheebed #

Effective Date: Feb 2022

Doc.No.F/ECS/UI (Ref: WI/ECS/10)

#### PATIALA LOCOMOTIVE WORKS, PATIALA

#### Testing & Commissioning Format For 3-Phase Locomotive fitted with IGBT based Traction Converter, Auxiliary Converter and TCN based VCU

Locomotive No.: 39397

Type of Locomotive: WAP-7/WAG-9HC

Page: 18 of 27

#### 5.3 Auxiliary Converter Commissioning

Switch on the high voltage supply and set up the loco in driving mode. Raise the panto. Close the VCB. Check that there is no earth fault in the auxiliary circuit, Switch off the VCB. Lower the panto. Create the earth fault in auxiliary circuit by making connection between wire no 1117(in HB2 cubicle) and earth. After 3 minutes a diagnostic message will come that "Earth fault auxiliary circuit."

5.3.1 Running test of 3 ph. auxiliary equipments

Switch on the 3 ph. auxiliary equipment one by one. Check the direction of rotation of each auxiliary machine and measure the continuous current and starting current drawn by them.

Name of the auxiliary machine	Typical phase current	Measured continuous phase current	Measured starting phase current
Oil pump transformer 1	9.8 amps	9.7	12.3
Oil pump transformer 2	9.8 amps	9.9	12.0
Coolant pump converter 1	19.6 amps	3.6	4.9
Coolant pump converter 2	19.6 amps	3.7	5-1
Oil cooling blower unit 1	40.0 amps	24.0	123.0
Oil cooling blower unit 2	40.0 amps	25.0	128.0
Traction motor blower 1	34.0 amps	30,0	170.0
Traction motor blower 2	34.0 amps	. 31.0	178.0
Sc. Blower to Traction motor blower 1	6.0 amps	2.9	19.0
Sc. Blower to Traction motor blower 1	6.0 amps	2.8	16.0
Compressor 1	25 amps at 0 kg/ cm <sup>2</sup> 40 amps at 10 kg/ cm <sup>2</sup>	28.0	146,0
Compressor 2	25 amps at 0 kg/ cm <sup>2</sup> 40 amps at 10 kg/ cm <sup>2</sup>	2.9.0	152.3

Effective Date: Feb 2022

PATIALA LOCOMOTIVE WORKS, PATIALA

(Ref: WI/ECS/10)

Testing & Commissioning Format For 3-Phase Locomotive fitted with IGBT based Traction Converter, Auxiliary Converter and TCN based VCU

Locomotive No.: 39397

Type of Locomotive: WAP-7/WAG-9HC

Page: 19 of 27

5.3.2 Performance of Auxiliary Converters

Measure the performance of the auxiliary converters through software and record it. BUR1 (Condition: Switch off all the load of BUR 1)- to be filled by commissioning engineer

Signal name	Description of the signal	Prescribed value	Monitored value	Value under Limit (Yes/No)
BUR1 7303 XUUN	Input voltage to BUR1	75% (10%=125V)	996~	Yey
BUR1 7303 XUUZ1		60% (10%=100V)	636W	793
BURI 7303 XUIZ1		0% (10%=50A)	1 Asp.	You
Box. ,sor			<del></del>	<u> </u>

BUR2 (Condition: Switch off all the load of BUR 2, Battery Charger on) to be filled by commissioning engineer of the firm.

Signal name	Description of the signal	Prescribed value by the firm	Monitored value	Value under Limit (Yes/No)
BUR2 7303-XUUN	Input voltage to BUR2	75% (10%=125V)	10014	Yey
BUR2 7303-XUUZ1	DC link voltage of BUR2	60% (10%=100V)	637	701
BUR2 7303-XUIZ 1	DC link current of BUR2	1% (10%=50A)*	7 Asp	Yey
BUR2 7303-XUILG	Current battery charger of BUR2	3% (10%=100A)*	21 Any	Yey
BUR2 7303-XUIB1	Current battery of BUR2	1.5%(10%=100A)*	1100	Ye
BUR2 7303 -XUUB	Voltage battery of BUR2	110%(10%=10V)	1100	Ya

<sup>\*</sup> Readings are dependent upon charging condition of the battery.

BUR3 (Condition: Switch off all the load of BUR 3, Battery Charger on) to be filled by commissioning engineer of the firm.

Signal name	Description of the signal	Prescribed set value by the firm	Monitored value	Value under limit (Yes/No)
BUR3 7303-XUUN	Input voltage to BUR3	75% (10%=125V	10021	teg
BUR3 7303- XUUZ1	DC link voltage of BUR3	60% (10%=100V)	637V	Yey
BUR3 7303-XUIZ 1	DC link current of BUR3	1% (10%=50A)*	7 Amp	re
BUR3 7303-XUILG	Current battery charger of BUR 3	3% (10%=100A)*	22001	Yey
BUR3 7303-XUIB1	Current battery of BUR 3	1.5%(10%=100A)*	12 pm	Yes
BUR3 7303-XUUB	Voltage battery of BUR 3	110%(10%=10V)	1107	Tey

Readings are dependent upon charging condition of the battery.

DOC.180.1 /ECC (Ref: WI/ECS/10)

Theeled of

#### PATIALA LOCOMOTIVE WORKS, PATIALA

Testing & Commissioning Format For 3-Phase Locomotive fitted with IGBT based Traction Converter, Auxiliary Converter and TCN based VCU

Locomotive No.: 383837

Type of Locomotive: WAP-7/WAG-9HC Page: 20 of 27

5.3.3 Performance of BURs when one BUR goes out

When any one BUR goes out then rest of the two BURs should take the load of all the

stilation level 3 of the locomotive.

Condition of	Loads on BUR1	Loads in BUR2	Loads in BUR3
BURs All BURs OK	Oil Cooling unit 1&2	TM blower1&2, TFP oil pump 1&2, SR coolant pump 1&2.	Compressor 1&2, Battery charger and TM Scavenger blower 1&2
BUR 1 out		Oil Cooling unit 1&2, TM blower1&2, TM Scavenger blower 1&2	Compressor 1&2,TFP oil pump 1&2, SR coolant pump 1&2 and Battery charger.
BUR 2 out	Oil Cooling unit 1&2, TM blower 1&2, TM Scavenger blower 1&2		Compressor 1&2, TFP oil pump 1&2, SR coolant pump 1&2 and Battery charger.
BUR 3 out	Oil Cooling unit 1&2, TM blower1&2, TM Scavenger blower 1&2	Compressor 1&2, TFP oil pump 1&2, SR coolant pump 1&2 and Battery charger.	

5.4 Auxiliary circuit 415/110

For checking earth fault detection, make a connection between wire no. 1218 and vehicle body. On switching on VCB, Earth fault relay 89.5 must pick up and after 3 minutes a message will come in the Diagnostic display that Earth Fault 415/110V Circuit

Switch on the 1 ph. auxiliary equipment one by one. Check the direction of rotation of each auxiliary machine and measure the continuous current and starting current drawn by them.

Name of the auxiliary machine	Typical phase current	Measured phase current	Measured starting current
Machine room blower 1	15.0 amps*	4.1	21.3
Machine room blower 2	15.0 amps*	4.2	20.0
Sc. Blower to MR blower 1	1.3 amps	1.1	4.3
Sc. Blower to MR blower 2	.1.3 amps	1.2	4.8
Ventilator cab heater 1	1.1 amps	1.3	1.3
Ventilator cab heater 2	1.1 amps	1.3	1.9
Cab heater 1	4.8 amps	5:4	5.5
Cab heater 2	4.8 amps	5.4	5.2

For indigenous MR blowers.

Effective Date: Feb 2022

(Ref: WI/ECS/10)

#### PATIALA LOCOMOTIVE WORKS, PATIALA

Testing & Commissioning Format For 3-Phase Locomotive fitted with IGBT based Traction Converter, Auxiliary Converter and TCN based VCU

Locomotive No.: 39387

Type of Locomotive: WAP-7/WAG-9HC

Page: 21 of 27

### 5.5 Hotel load circuit (Not applicable for WAG-9HC)

For WAP-7 locomotive with Hotel load converter refer to Annexure-HLC

#### 5.6 Traction Converter Commissioning

#### This test is carried out in association with Firm.

Traction converter commissioning is being done one at a time. For testing Converter 1, switch off the traction converter 2 by switch bogie cut out switch 154. For testing Converter 2, switch off the traction converter 2 by switch bogie cut out switch 154. Isolate the harmonic filter also by switch 160. Start up the loco by one converter. Follow the functionality tests.

For Converter 1 Test Function	Results desired	Result obtained
Measurement of charging and pre-charging and charging of DC Link of Converter 1	Traction converter manufacturer to declare the successful operation and demonstrate the same to the PLW supervisor.	cheehed ot
Measurement of discharging of DC Link of Converter 1	Traction converter manufacturer to declare the successful operation and demonstrate the same to the PLW supervisor.	cheebed ok
Earth fault detection on positive potential of DC Link of Converter 1	Traction converter manufacturer to declare the successful operation and demonstrate the same to the PLW supervisor.	cheebeal Ok
Earth fault detection on negative potential of DC Link of Converter 1	Traction converter manufacturer to declare the successful operation and demonstrate the same to the PLW supervisor.	Checked ok
Earth fault detection on AC part of the traction circuit of Converter 1	Traction converter manufacturer to declare the successful operation and demonstrate the same to the PLW supervisor.	checked or
Pulsing of line converter of Converter 1	Traction converter manufacturer to declare the successful operation and demonstrate the same to the PLW supervisor.	Checked Ok
Pulsing of drive converter of Converter 1	Traction converter manufacturer to declare the successful operation and demonstrate the same to the PLW supervisor.	checked ox

Effective Date: Feb 2022

2022

#### PATIALA LOCOMOTIVE WORKS, PATIALA

<u>Testing & Commissioning Format For 3-Phase Locomotive fitted with</u>
<u>IGBT based Traction Converter, Auxiliary Converter and TCN based VCU</u>

Locomotive No.: 3 9 3 97

Type of Locomotive: WAP-7/WAG-9HC Page: 22 of 27

(Ref: WI/ECS/10)

For Converter 2	= the Level in cognopce	Result obtained
Test Function	Results desired in sequence	Hebert Chamine.
charging and pre- charging and charging of DC Link of Converter	Traction converter manufacturer to declare the successful operation and demonstrate the same to the PLW supervisor.	chechool ok
Measurement of discharging of DC Link of Converter 2	Traction converter manufacturer to declare the successful operation and demonstrate the same to the PLW supervisor.	cheebood ox
positive potential of DC Link of Converter 2.	Traction converter manufacturer to declare the successful operation and demonstrate the same to the PLW supervisor.	Cheebool ix
negative potential of DC Link of Converter 2.	Traction converter manufacturer to declare the successful operation and demonstrate the same to the supervisor/v	Chechedok
AC part of the traction circuit of Converter 2.	Traction converter manufacturer to declare the successful operation and demonstrate the same to the PLW supervisor.	Checked ok
Pulsing of line converter of Converter 2.	Traction converter manufacturer to declare the successful operation and demonstrate the same to the PLW supervisor.	checked th
Pulsing of drive converter of Converter 2	Traction converter manufacturer to declare the successful operation and demonstrate the same to the PLW supervisor.	chicked ox

Effective Date: Feb 2022

PATIALA LOCOMOTIVE WORKS, PATIALA

Testing & Commissioning Format For 3-Phase Locomotive fitted with IGBT based Traction Converter, Auxiliary Converter and TCN based VCU

Locomotive No.: 38387

Type of Locomotive: WAP-7/WAG-9HC

Page: 23 of 27

(Ref: WI/ECS/10)

### 5.7 Test protective shutdown SR

Test Function	Results desired in sequence	Result obtained	
Measurement of protective shutdown by Converter 1 electronics.	Start up the loco with both the converter. Raise panto. Close VCB. Move Reverser handle to forward or reverse. Remove one of the orange fibre optic feedback cable from converter 1Check that converter 1 electronics produces a protective shut down.  • VCB goes off • Priority 1 fault mesg. on DDU appears	cheebed ok	
Measurement of protective shutdown by Converter 2 electronics.	Start up the loco with both the converter. Raise panto. Close VCB.  Move Reverser handle to forward or reverse. Remove one of the orange fibre optic feedback cable from converter 2. Check that converter 2 electronics produces a protective shut down.  • VCB goes off • Priority 1 fault mesg. on diagnostic display appears  Disturbance in Converter 2	checked ok	

#### 5.8 Test Harmonic Filter

Switch on the filter by switch 160

Test Function	Results desired in sequence	Result obtained
Measurement of filter currents	Start up the loco with both the converter. Raise panto. Close VCB. Move Reverser handle to forward or reverse. Apply a small value of TE/BE by moving the throttle.  • FB contactor 8.41 must open.	checked ox

(Ref: WI/ECS/10)

#### PATIALA LOCOMOTIVE WORKS, PATIALA

<u>Testing & Commissioning Format For 3-Phase Locomotive fitted with</u>
<u>IGBT based Traction Converter, Auxiliary Converter and TCN based VCU</u>

Locomotive No.: 38387

Type of Locomotive: WAP-7/WAG-9HC

Page: 24 of 27

	<ul> <li>FB contactor 8.2 must close.</li> <li>FB contactor 8.1 must close</li> <li>Check the filter current in diagnostic laptop</li> <li>Bring the TE/BE throttle to O</li> <li>Switch off the VCB</li> <li>FB contactor 8.1 must open.</li> <li>FB discharging contactor 8.41 must close</li> <li>Check the filter current in diagnostic laptop</li> </ul>	Checked ok
Test earth fault detection harmonic filter circuit.	Make a connection between wire no. 12 and vehicle body. Start up the loco. Close VCB.  • Earth fault relay 89.6 must pick up.  • Diagnostic message comes that - Earth fault in harmonic filter circuit	Chechedok
Test traction motor speed sensors for both bogie in both cabs	Traction converter manufacturer to declare the successful operation and demonstrate the same to the supervisor/ PLW	ok

#### 5.9 Test important components of the locomotive

Items to be tested	Description of the test	Monitored value/remarks	
Speedometer	VCU converter manufacturer to declare the successful operation and demonstrate the same to the supervisor/ PLW	checked ox	
Time delay module of MR blower	The time after which the starting capacitor for MR blower should go off the circuit should be set to 10-12 seconds	Checked ox	
Ni-Cd battery voltage	At full charge, the battery voltage should be 110V DC.	cheebed of	
Flasher light	From both cab flasher light should blink at least 65 times in one minute.	cheebed of	
Head light	Head light should glow from both cabs by operating ZLPRD. Dimmer operation of headlight should also occur by operating the switch ZLPRD.	cheched ox	

Effective Date: Feb 2022

### PATIALA LOCOMOTIVE WORKS, PATIALA

Testing & Commissioning Format For 3-Phase Locomotive fitted with IGBT based Traction Converter, Auxiliary Converter and TCN based VCU

Locomotive No.: 39387

Type of Locomotive: WAP-7/WAG-9HC

Page: 25 of 27

DOC.NO.P/ECS/VI

(Ref: WI/ECS/10)

Marker light	Both front and tail marker light should glow from both the cabs	cheabed ok
Cab Light	Cab light should glow in both the cabs by operating the switch ZLC	checked ox
Spot lights	Both Drivers and Asst. Drivers Spot light should glow in both cabs by operating ZLDD	checked ok
Instrument lights	Instrument light should glow from both cab by operating the switch ZLI	Chesidot
Illuminated Push button	All illuminated push buttons should glow during the operation	cheehod ot
Contact pressure of the high rating contactors	The contact pressure of FB contactors (8.1, 8.2) is to be measured  Criteria:  The minimum contact pressure is 54 to 66  Newton.	For contactor 8.1:
Crew Fan	All crew fans should work properly when VCB of the loco is switched on. The airflow from each cab fan is to be measured.  Criteria:  The minimum flow of air of cab fan should be 25 m <sup>3</sup> /minute	Cab 1 LHS: Cab 1 RHS: Checked Cab 2 LHS: Cab 2 RHS:

#### 6.0 Running Trial of the locomotive

SN	Description of the items to be seen during trail run	buring trail run		
1	Cab activation in driving mode	No fault message should appear on the diagnostic panel of $e$ the loco.	heebod o	
	Loco charging	loco. Raise MR pressure to 10 Kg/cm <sup>2</sup> , BP to 5 Kg/cm <sup>2</sup> , FP to 6 Kg/cm <sup>2</sup> .	Acched	
3.	Check function of Emergency push stop.	This switch is active only in activated cab. By pushing this switch VCB should open & pantograph should be lowered.	Checked	
4.	Check function of BPCS.	<ul> <li>Beyond 5 kmph, press BPCS, the speed of loco should be constant.</li> <li>BPCS action should be cancelled by moving TE/BE throttle, by dropping BP below 4.75 Kg/cm<sup>2</sup>, by pressing BPCS again.</li> </ul>	cheched	
5.	Check train parting operation of the Locomotive.	Operate the emergency cock to drop the BP Pressure LSAF should glow.	Checker	

(Ref: WI/ECS/10)

### PATIALA LOCOMOTIVE WORKS, PATIALA

# <u>Testing & Commissioning Format For 3-Phase Locomotive fitted with</u> <u>IGBT based Traction Converter, Auxiliary Converter and TCN based VCU</u>

Locomotive No.: 39392

Type of Locomotive: WAP-7/WAG-9HC

Page: 26 of 27

Check vigilance	Set the speed more than 1.5 kmph and ensure that	
operation of the	brakes are released i.e. BC < 1 Kg/cm <sup>2</sup> .	.
locomotive	For 60 seconds do not press vigilance foot switch or	
	switch then	
		cheeland
·	vigilance foot switch further for 8 seconds then:-	
	•	
	•	
	acknowledge RPVR and press & release vigilance	
	<u> </u>	
Charlestart/rup interlock		Cheaped of
Check Starty run intersect	<b>†</b>	WA
	1	
		cheched
1	1	Checaga
	• With emergency cock (BP < 4.75 Kg/cm <sup>2</sup> ).	
Check traction interlock	Switch of the brake electronics. The	
	Tractive /Braking effort should ramp down, VCB	Checkeo
	should open and BP reduces rapidly.	Checked
Check regenerative	Bring the TE/BE throttle to BE side. Loco speed	a lan had
braking.	should start reducing.	Checo
Check for BUR	In the event of failure of one BUR, rest of the two	
redundancy test at	BURs can take the load of all the auxiliaries. For this	
ventilation level 1 & 3 of	switch off one BUR.	Cheebal
loco operation	Auxiliaries should be catered by rest of two BURs.	
	Switch off the 2 BURs; loco should trip in this case.	
Check the power	Create disturbance in power converter by switching	
converter	off the electronics. VCB should open and converter	Checheel
isolation test	should get isolated and traction is possible with	
	another power converter.	
	Check start/run interlock  Check traction interlock  Check regenerative braking. Check for BUR redundancy test at ventilation level 1 & 3 of loco operation  Check the power converter	brakes are released i.e. BC < 1 Kg/cm².  For 60 seconds do not press vigilance foot switch or sanding foots switch or TE/BE throttle or BPVG switch then  • Buzzer should start buzzing. • LSVW should glow continuously.  Do not acknowledge the alarm through BPVG or vigilance foot switch further for 8 seconds then: • Emergency brake should be applied automatically. • VCB should be switched off. Resetting of this penalty brake is possible only after 32 seconds by bringing TE/BE throttle to 0 and acknowledge BPVR and press & release vigilance foot switch.  Check start/run interlock  Check start/run interlock  Check traction interlock  Check traction interlock  Check traction interlock  Check regenerative braking.  Check for BUR redundancy test at ventilation level 1 & 3 of loco operation  Check the power converter isolation test  Check the power converter isolation test  Check the power converter isolation test

Effective Date: Feb 2022

(Ref: WI/ECS/10)

#### PATIALA LOCOMOTIVE WORKS, PATIALA

<u>Testing & Commissioning Format For 3-Phase Locomotive fitted with</u>
<u>IGBT based Traction Converter, Auxiliary Converter and TCN based VCU</u>

Locomotive No.: 39387

Type of Locomotive: WAP-7/WAG-9HC

Page: 27 of 27

# 7.0 Final check list to be verified at the time of Loco dispatch

Condition /Operations of the following items are to be checked:

SN	Item	Cab-1	Cab-2	Remarks
1	Head lights	ok	de	
2	Marker Red	ok	ot	
- 3	Marker White	0.4	ok	
4	Cab Lights	ok	ok	
5	Dr Spot Light	ok	ok	cheebed wershing
6	Asst Dr Spot Light	ok	8k	
7	Flasher Light	ok	04L	
8	Instrument Lights	ok	ok	
9	Corridor Light	OK	0¢	
10	Cab Fans	OK	ok	
11	Cab Heater/Blowers	.61	øk.	
12	All Cab Signal Lamps Panel 'A'	0×	2015	

## PATIALA LOCOMOTIVE WORKS, PATIALA

# Testing & Commissioning Format for 2x500KVA IGBT based Hotel Load Converter for 3-phase Electric Locomotives

Locomotive No.: 39397	Page: 1 of 6
Type of Locomotive: いかアラ	
Make of Hotel Load Converter:AAL	<u> </u>
Details of Equipment: -	

Equipment	SI. No	Equipment	SI. No
HLC1	0524020037	IV Coupler CAB1 ALP	
HLC2	0524020038	IV Coupler CAB1 LP	
Converter-1	0524020037	IV Coupler CAB2 ALP	
Converter-2	6524020038	IV Coupler CAB2 LP	
UIC Coupler for Hotel Load Converter (353.3/2 CAB2)		UIC Coupler for Hotel Load Converter (353.3/3 CAB1)	V

#### 1. Polarity test of Hotel Load Winding:

Apply 198 /140 to the primary winding of the transformer (at 1U; wire no. 2 at surge arrestor and at 1V; wire no. 100 at earthing choke). Measure the output voltage and compare the phase of the following of the transformer.

Output Winding Nos.	Description of winding	Prescribed Output Voltage &Polarity with input supply	Measured Output	Measured Polarity
2UH1 & 2VH1	For Hotel load between cable 91- 94	5.9 ;4.2 and same polarity	BL	0 K
2UH2 & 2VH2	For Hotel load between cable 91A- 94A	5.9 ,4.2 and same polarity	DK	OR

#### 2. Visual Inspection:

# Fitment of Units and Earthing to Sub-assemblies

Verify the following Equipments Fitment and grounding cables are connected to Locomotive body.

SI. No.	Equipment Name	Unit Fitment (Yes/No)	Provision of Earthing (Yes/No)
• 1	HLC1	Yes.	Yes
2	HLC2	~	6
3	Output Contactor unit1 HLC1	~1	
4	Output Contactor unit2 HLC2	ч	и
5	IV Coupler CAB1 ALP	7	5
6	IV Coupler CAB1 LP	1	7
7	IV Coupler CAB2 ALP	-	c,
8	IV Coupler CAB2 LP	и	4
9	UIC Coupler for Hotel Load Converter (353.3/3 CAB1)	1	01
10	UIC Coupler for Hotel Load Converter (353.3/2 CAB2)	ч	ч
11	CT (LEM sensor) under HLC1	u	y
12	CT(LEM sensor) under HLC2	4	9

# 3. Cable Routing and Laying

# 3.1 Control cable routing and layout

Verify the connections, tightness and cable routing of the following Control cable.

il.	Cables Details	Performed (Yes/No)
lo.	From Wago SB1 to HLC1 are connected as per wiring	
1	format	408
		/
2	From SB1 to UIC Coupler Hotel Load Converter (353.3/3	•
_	CAB2) through Bayonet connector XK22HL:01(22pin)is connected as per wiring format	L
	From SB1 wago(XF22S:01/53) to IV coupler CAB1 ALP	4
3	are connected as per wiring format	-2
4	From SB1 wago(XF22S:01/54) to IV coupler CAB1 LP	
	are connected as per wiring format	4
5	From Wago SB2 to HLC2 are connected as per wiring	
_	format	4
6	From SB2 to UIC Coupler Hotel Load Converter (353.3/2	
	CAB2) through Bayonet connector XK77HL:02 (22 pin) is	4
	connected as per wiring format	
7	From SB2 wago (XF77S:01/53) to IV coupler CAB2 ALP	
	are connected as per wiring format	4
8	From SB2 wago (XF77S:01/54) to IV coupler CAB2 LP	
	are connected as per wiring format	4
9	From HLC1 to Contactor unit 1 through 4 Core Cable are	
	connected as per wiring format	9
_		
10	From HLC2 to Contactor unit 2 through 4 Core Cable are	
	connected as per wiring format	4
11	From SB to VCU are connected as per wiring format	
		4
12	From CT (HLC1 LEM sensor) to SR1 are connected as	
	per wiring format	9
13	From CT (HLC2 LEM sensor) to SR2 are connected as	
	per wiring format	7

#### 3.2 Power cable routing and layout

Verify the connections, tightness and cable routing of the following Power cable.

SI. No.	Cables Details	Performed Yes/No)
1	From Transformer to HLC1(2UH1 & 2VH1) are connected as per wiring format	403
2	From Transformer to HLC2(2UH2 &2VH2) are connected as per wiring format	9
3	From HLC1 to Output Contactor unit1 are connected as per wiring format	
4	From HLC 2 to Output Contactor unit 2 are connected as per wiring format	٤
5	From Output Contactor unit 1 to IV Coupler CAB1 ALP and IV Coupler CAB2ALP through Junction box are connected as per wiring format	٧
6	From Output Contactor unit 2 to IV Coupler CAB2 LP and IV Coupler CAB1 LP through Junction box are connected as per wiring format	n

#### 4. Continuity test:

Check the continuity test for the External connections made to Equipments.

Note: This continuity test should be done before power ON the Locomotive Battery.

#### 4.1 Control cable continuity

SI. No.	Cables Details	Performed (Yes/No)
1	From Wago SB1 to HLC1 are connected as per wiring format	7.5
2	From SB1 to UIC Coupler Hotel Load Converter (353.3/3 CAB2) through Bayonet connector XK22HL:01(22pin)is connected as per wiring format	4
3	From SB1 wago(XF22S:01/53) to IV coupler CAB1 ALP are connected as per wiring format	7
4	From SB1 wago(XF22S:01/54) to IV coupler CAB1 LP are connected as per wiring format	4
5	From Wago SB2 to HLC2 are connected as per wiring format	4
6	From SB2 to UIC Coupler Hotel Load Converter (353.3/2 CAB2) through Bayonet connector XK77HL:02(22pin) is connected as per wiring format	4
7	From SB2 wago (XF77S:01/53) to IV coupler CAB2 ALP are connected as per wiring format	9
8	From SB2 wago(XF77S:01/54) to IV coupler CAB2 LP are connected as per wiring format	2
.9	From HLC1 to Contactor unit 1 through 4 Core Cable are connected as per wiring format	9
10	From HLC2 to Contactor unit 2 through 4 Core Cable are connected as per wiring format	4
11	From SB to VCU are connected as per wiring format	ч
12	From HLC1 LEM sensor to SR1 are connected as per wiring format	7
13	From HLC2 LEM sensor to SR2 are connected as per wiring format	1

Page: 5 of 6

#### 4.2 Power cable continuity

These cables continuity should be checked before mounting of converter in the locomotive.

SI. No.	Cables Details	Performed (Yes/No)
1	From Transformer to HLC1(2UH1 & 2VH1) are connected as per wiring format	Yes
2	From Transformer to HLC2(2UH2 &2VH2) are connected as per wiring format	·
3	From HLC1 to Output Contactor unit1 are connected as per	4
4	From HLC 2 to Output Contactor unit 2 are connected as per	9
5	From Output Contactor unit 1 to IV Coupler CAB1 ALP and IV Coupler CAB2ALP through Junction box are connected as per wiring format	4
6	From Output Contactor unit 2 to IV Coupler CAB1 LP and IV Coupler CAB2 LP through Junction box are connected as per wiring format	1

#### 5. Battery power ON

#### Tests Supply Voltages

Remove all Control cable connectors (Analog and Digital Input/output connectors) from HLC1, HLC2. While Switch ON Battery supply observe is there any MCBs tripping. Wait for one or two minutes after switching ON Circuit breaker(MCB1) and observe for any overheating symptoms like smell, smoke, temperature etc. from the wire bunches. If any such symptoms are noticed, there might be a short circuit in the wire bunch. Check up once again continuity wherever suspected. After that check the Voltage levels at all equipments connectors as mentioned below.

Test Details	Acceptance	Observations
Voltage Level at HLC1:  I. Between wago terminal XF22S:03/54 and XF22S:03/58  II. Between wago terminal XF22S:03/53 and XF22S:03/58	~110VDC	OV
Voltage Level at HLC2: I. Between wago terminal XF77S:03/52 and XF77S:03/56 II. Between wago terminal XF77S:03/51 and XF77S:03/56	~110VDC	Ore

**Note:** After Above tests switch off the Power and restore all removed connectors and once again switch ON the 110 V Supply and ensure that no MCB tripping due to abnormality.

Page: 6 of 6

#### 6. Converter operation (ON/OFF) test

Power supply is directly available to the Hotel Load Converter via Hotel Load Converter winding (2UH1-2VH1) and (2UH2-2VH2). As soon as BLDJ is closed power will be available to the Hotel Load Converter. Connect the test jig of Hotel Load Converter to the UIC and IV Coupler. Charge the locomotive and switch on the BLHO, LSHO indication should glow. Hotel Load Converter screen will show message "waiting for ON command". One by one Hotel Load Converter can be switched on by test jig. Finally both the Hotel Load Converter should be turned out simultaneously. Observe the flow of air from the air duct, this will ensure that Hotel Load Converter is ON. Both the Hotel Load Converters are ON, then voltage and frequency should be measured as per the table below:-

Converters should run without any irregularities.

otel Load Convert	er 1		
Output Voltage		· ·	Output Frequency
U-V	V-W	U-W	(Hz)
00	OK.	· ox	8k

otel Load Converte	er Z		
Output Voltage			Output Frequency
U-V	V-W	U-W	(Hz)
08	O	24	OK.

#### 7. Earth Fault Test

- **7.1 Input Earth Fault:-**Ground the input terminal of the Hotel Load Converter using a proper resistance and then turn on the Hotel Load Converter. The converter should trip with the message "Input earth fault".
- **7.2 Output Earth Fault:-**Ground the output terminal of the Hotel Load Converter using a proper resistance and then turn on the Hotel Load Converter. The converter should trip with the message "Output earth fault".

Note: These to be done for the both the converters (HLC1 and HLC2) separately.

Page: 33/A

33 A

## Status of RDSO modifications

LOCO NO: 39397

Sn	Modification No.	Description	Remarks
1	RDSO/2008/EL/MS/0357	Modification in control circuit of Flasher Light and Head Light of three phase electric locomotives.	øk/Not Ok
	Rev.'0' Dt 20.02.08 RDSO/2009/EL/MS/0377	Modification to voltage sensing circuit in electric	OK/Not Ok
	Rev.'0' Dt 22.04.09	Rev.'0' Dt 22.04.09 locomotives.	
3.	RDSO/2010/EL/MS/0390 Rev.'0' Dt 31.12.10	three phase locomotives to improve reliability.  Removal of interlocks of control circuit contactors no. 126	Ok/Not Ok  OK/Not Ok
4.	RDSO/2011/EL/MS/0399 Rev.'0' Dt 08.08.11	from MCPA circuit.  Modification sheet for shifting the termination of \$GKW, 1.8	SK/NOT OK
5.	RDSO/2011/EL/MS/0400 Rev.'0' Dt 10.08.11	KV, 70 sq mm cables and 2x2.5 sq mm cables housed in lower portion of HB2 panel and provision of Synthetic resin bonded glass fiber sheet for three phase locomotives.	QK/Not Ok
6.	RDSO/2011/EL/MS/0401 Rev.'0' Dt 10.08.11	Modification sheet for relaying of cables in HB-2 pariel of three phase locomotives to avoid fire hazards.	Øk/Not Ok
7.	RDSO/2011/EL/MS/0403 Rev.'0' Dt 30.11.11	Auto switching of machine room/corridor lights to avoid	OK/Not Ok
8.	RDSO/2012/EL/MS/0408	Modification of terminal connection or heater cum blower	QK/Not Ok
9.	RDSO/2012/EL/MS/0411 Rev.'1' dated 02.11.12		OK/Not Ok
10	RDSO/2012/EL/MS/0413 Rev.'1' Dt 25.04.16	Paralleling of interlocks of EP contactors and auxiliary contactors of three phase locomotives to improve reliability.	QK/Not Ok
11	RDSO/2012/EL/MS/0419 Rev.'0' Dt 20.12.12		Øk/Not Ok
12	RDSO/2013/EL/MS/0420 Rev.'0' Dt 23.01.13	Modification sheet to provide mechanical locking arrangement in Primary Over Current Relay of three phase	9K/Not Ok
13	RDSO/2013/EL/MS/0429 Rev.'0' Dt 22.05.13	Modification sheet for improving illumination of head light in dimmer mode in three phase electric locomotives.	Øk/Not Ok
14	RDSO/2013/EL/MS/0420 Rev.'0' Dt 18.07.13	6 Modification sheet of Bogie isolation rotary switch in three phase electric locomotives.	Ok/Not Ok
15	RDSO/2013/EL/MS/042 Rev.'0' Dt 23.10.13	RDSO/2013/EL/MS/0427 Modification sheet for MCP control in three phase electric	
16	RDSO/2013/EL/MS/042 Rev. '0' Dt 10.12.13	8 Modification sheet for relocation of earth fault relays for harmonic filter and hotel load along with its resistors in three phase electric locomotives.	QR/Not OK
17	RDSO/2014/EL/MS/043 Rev.'0' Dt 12.03.14	2 Removal of shorting link provided at c-d terminal of over current relay of three phase electric locomotives.	
18	RDSO/2017/EL/MS/046 Rev.'0' Dt 25.09.17	4 Provision of Auxiliary interlock for monitoring of Harmonic filter ON (8.1)/adoption (8.2) Contactor in GTO/IGBT locomotives.	9k/Not Ok
19	RDSO/2017/EL/MS/046 Rev.'0' Dt 07.12.17	77 Modification in blocking diodes to improve reliability in three phase electric locomotives.	7
20			Qk/Not Ok
21			Øk/Not Ok



Signature of JE/SSE/ECS

#### PLW/PATIALA

## PNEUMATIC TEST PARAMETERS OF 3-PHASE ELECTRIC LOCOMOTIVES

(As per DG/RDSO/LKO's letter No.-EL/3.2.19/3phase, dated-29.03.2012)

SN	Parameters	Reference	Value	Result
	Brake Panel: Knorr Bremse			
1.0	Auxiliary Air supply system (Pantograph & VCB)			
1.1	Ensure, Air is completely vented from pantograph			0
	Reservoir (Ensure Panto gauge reading is Zero)			
1.2	Turn On BL Key. Now MCPA starts.		60 sec. (Max.)	
	Record pressure Build up time (8.0 kg/cm2)		120 sec (Knorr)	114 sec
1.3	Auxiliary compressor safety Valve 23F setting	Faiveley Doc. No.	8.5±0.25kg/cm2	8.60 Kg/cm2
		DMTS-014-1, 8 CLW's	-	
		check sheet no.		
		F60.812 Version 2		
1.4	Check VCB Pressure Switch Setting	CLW's check sheet	Opens 4.5±0.15	4.55 Kg/cm2
		no. F60.812 Version	kg/cm2, closes	
		2	5.5±0.15 kg/cm2	5.55 Kg/cm2
1.5	Set pantograph Selector Switch is in Auto, Open pan-1&2 Is	olating Cocks & KABA co		, <u> </u>
1.6	Set Cab-1 Pan UP in Panel A.		Observed Pan-2	ок
			Rises.	
1.7	Close Pan-2 isolating Cock		Panto-2 Falls Down	ОК
4.0	Open Pan -2 isolating Cock		Panto-2 Rises	
1.8	Record Pantograph Rise time		06 to 10 seconds	9 Sec
1.9	Record Pantograph Lowering Time		06 to 10 seconds	8 Sec
1.10	Panto line air leakage		0.7 kg/cm2 in 5	0.20 kg/cm2
4.44			Min.	in 5 Min.
2.0	High Reach Panto emergency test and reset.		NA	NA
	Main Air Supply System			
2.1	Ensure, Air is completely vented from locomotive. Drain	Theoretical		
	out all the reservoirs by opening the drain cocks and then	calculation and		
	closed drain cocks. MR air pressure build up time by each	test performed by		
	compressor from 0 to 10 kg/cm2.	Railways.	i) 7 mins Max.	6 min 9 25
	i) with 1750 LPM compressor ii) with 1450 LPM compressor		ii) 8.5 mins Max.	6 min. & 25
	ii) with 1430 trivi compressor		ii) 6.5 iiiiis iviax.	sec.
2.2	Drain air below MR 8 kg/cm2 to start both the		Check Starting of	Ok
	compressors		both compressors	
2.3	Drain air from main reservoir up to 7 kg/cm2. Start		30 Sec. (Max)	CP1-28 Sec
	compressors, Check pressure build time of individual		, 1	
	compressor from 8 kg/cm2 to 9 kg/cm2			CP2-27 Sec
2.4	Check Low MR Pressure Switch Setting (37)	D&M test spec.	Closes at 6.40±0.15	6.40 Kg/cm2
		MM3882 &	kg/cm2 Opens at	
		MM3946	5.60±0.15kg/cm2	5.6 Kg/cm2
2.5	Check compressor Pressure Switch RGCP setting (35)	D&M test spec.	Opens at 10±0.20	10.1 Kg/cm2
		MM3882 &	kg/cm2, Closes at	8.1 Kg/cm2
		MM3946	8±0.20 kg/cm2	
2.6	Run both the compressors Record Pressure build up time	Trial results	3.5 Minutes Max.	3.20 minute

#### PLW/PATIALA

Loco No.: 39397

2.7	Check unloader val	ve operation time				Approx. 12 Sec.	10 sec
2.8	Check Auto Drain V	alve functioning (12	24 & 87)			Operates when Compressor starts	ok
2.9	Check CP-I delivery	safety valve setting	(10/1). Run CP	D&M t	est spec.	11.50±0.35	11.50
	Direct by BLCP.			MM3882	& MM3946	kg/cm2	Kg/cm2
2.10	Check CP-2 delivery	, safety valve setting	g (10/2). Run CP	D&M t	est spec.	11.50±0.35	11.50
	direct by BLCP			MM3882	& MM3946	kg/cm2	Kg/cm2
2.11	Switch 'OFF' the co	mpressors and ensu	re that the safety	D&M t	est spec.		Ok
	valve to reset at pressure 1.2 kg/cm2 less than opening pressure.			MM3882	& MM3946		
2.12	BP Pressure: Switch 'OFF' compressor, Drain MR Pressu by drain cock of 1" Main Reservoir, Start Compressor, check setting pressure of Duplex Check Valve 92F.			CLW's chec F60.812 Ve	ck sheet no. ersion 2	5.0±0.10kg/cm2	5.0 Kg/cm2
2.13	FP pressure: Fit Test Gauge in Test point 107F FPTP. Open isolate of 136F. Check pressure in Gauge.  Air Dryer Operation			CLW's chec F60.812 Ve	ck sheet no. ersion 2	6.0±0.20kg/cm2	6.0 Kg/cm2
3.0	Air Dryer Operati	ion					
3.1	Open Drain Cock 90 of 2 <sup>nd</sup> MR to start Compressor, leave open for Test Check Air Dryer Towers to change.		•			Tower to change every minute	Ok
3.2	Check Purge Air Stops from Air Dryer at Compressor stops				,,	Ok	
3.3	Check condition of humidity indicator				Blue	Blue	
4.0	Main Reservoir Leakage Test						Ok
4.1	Put Auto Brake (A-9 leakage from both	9) in full service, Che cabs.	eck MR Pressure air		est spec. & MM3946	Should be less than 1 kg/cm2 in 15 minutes	0.25 Kg/cm2 in 15 minutes
4.2	Check BP Air leakag	ge		D&M test spec. MM3882 & MM3946		0.15 kg/cm2 in 5 minutes	0.05 Kg/cm2 in 5 minutes
5.0	Brake Test (Auto	matic Brake opera	ation)				
5.1	Record Brake Pipe	& Brake Cylinder pro	essure at Each Step				
	Check proportional	lity of Auto Brake sy	stem		ck sheet no. Version 2		
	Auto controller position	BP Pressure kg/cn	Pressure kg/cm2		& WAP-7)	BC (WAP-5) Kg/cm2	
		Value	Result	Value	Result	Value	Result
	Run	5±0.1	5.0 Kg/cm2	0.00	0.00 Kg/ cm2	0.00	-
	Initial	4.60±0.1	4.55 Kg/cm2	0.40±0.1	0.40Kg/ cm2	0.75±0.15	-
	Full service	3.35±0.2	3.35 Kg/cm2	2.50±0.1	2.5Kg/ cm2	5.15±0.30	-
	Emergency	Less than 0.3	0.3 Kg/cm2	2.50±0.1	2.5Kg/ cm2	5.15±0.30	-
ļ	I			Į	Į		

## PLW/PATIALA

Loco No.: 39397

	T	T = 2	T	T
5.2	Record time to BP pressure drop to 3.5 kg/cm2 Ensure	D&M test spec.	8±2 sec.	8 Sec
	Automatic Brake Controller handle is Full Service from Run	MM3882 & MM3946		
5.3	Operate Asst. Driver Emergency Cock,	D&M test spec.	BP pressure falls	
		MM3882 & MM3946	to Below 2.5	ОК
			kg/cm2	
5.4	Check brake Pipe Pressure Switch 69F operates	CLW's check sheet no.	Closes at BP	4.10
		F60.812 Version 2	4.05- 4.35	Kg/cm2
			kg/cm2	
			Opens at BP	
			2.85-3.15 kg/cm2	3.05
				g/cm2
5.5	Move Auto Brake Controller handle from Running to	D&M test spec.		
	Emergency BC filling time from 0.4 kg/cm2 i.e. 95% of	MM3882 & MM3946		
	Max. BC developed			
	WAP5 – BC 5.15 $\pm$ 0.3 kg/cm2 apply time		4±1 sec.	
	WAP7 - BC 2.50 ± 0.1 kg/cm2		7.5±1.5 sec.	7 sec
	WAG9 - BC 2.50 ± 0.1 kg/cm2		21±3 sec.	
5.6	Move Auto Brake Controller handle to full service and	D&M test spec.		
	BP pressure 3.5 kg/cm2. Move Brake controller to	MM3882 & MM3946		
	Running position BC Release time to fall BC Pressure			
	up to 0.4 kg/cm2 i.e. 95% of Max. BC developed			
	BC release Time			
	WAP7		17.5±2.5 sec.	16.5 sec
	WAG9		52±7.5 sec.	10.5 360
5.7	Move Auto Brake Controller handle to Release, Check	CLW's check sheet no.	60 to 80 Sec.	70 Sec
J./	, and the second		60 to 80 sec.	/0 Sec
5.8	BP Pressure Steady at 5.5± 0.2 kg/cm2 time.	F60.812 Version 2	DD	
5.8	Auto Brake capacity test : The capacity of the A9 valve	RDSO Motive power	BP pressure	
	in released condition must conform to certain limit in	Directorate report no.	should not fall	
	order to ensure compensation for air leakage in the	MP Guide No. 11 July,	below 4.0	
	train without interfering with the automatic	1999 Rev.1	kg/cm2 with in	4.9
	functioning of brake.		60 Sec.	Kg/cm2
	* Allow The MR pressure to build up to maximum			
	stipulated limit.			
	* Close brake pipe angle cock and charge brake pipe to			
	5 kg/cm2 by A 9 (Automatic brake controlling) at run			
	position.			
	* Couple 7.5 dia leak hole to the brake hose pipe of			
	locomotive. Open the angle cock for brake pipe.			
	The test shall be carried out with all the compressors			
	in working condition.			
5.9	Keep Auto Brake Controller (A-9) in Full Service. Press		BC comes to '0'	0
	Driver End paddle Switch (PVEF)			
6.0	Direct Brake (SA-9)			
6.1	Apply Direct Brake in Full Check BC pressure			
	WAG9/WAP7	CLW's check sheet no.	3.5±0.20 kg/cm2	3.5
	WAP5	F60.812 Version 2	5.15±0.3 kg/cm2	Kg/cm2
6.2	Apply Direct Brake, Record Brake Cylinder charging	D&M test spec.	8 sec. (Max.)	6 Sec
U.Z	Apply Direct Drake, necord brake cyllider charging	Dain rest shee.	O Sec. (IVIAX.)	0 360

time MM3882 & MM3946

Page 4 of 4

## **PLW/PATIALA**

Loco No.: 39397

6.3	Check Direct Brake Pressure switch 59 (F)	D&M test spec. MM3882 & MM3946	0.2.±0.1 kg/cm2	0.20 kg/cm2
6.4	Release direct brake & BC Release time to fall BC pressure up to 0.4 kg/cm2		10 -15 Sec.	13 Sec
7.0	Modified System Software (only for CCB)			
7.1	Bail-off de-activated during emergency by any means			Now de- activated
7.2	DPWCS and Non-DPWCS mode enabled		Multi Loco	
7.3	TCAS and Non-TCAS mode enabled		Not Yet Launched	Presently
7.4	Penalty brake application deactivated for Fault code 113 (FC 113) and CCB health signal will not drop to avoid loco detention/failure. The Brake Electronics Failure "message will not generate on DDS.	- RDSO letter no.	Pressure Setting Needed is12 kg/sqcm causing mismatching with standard Pr Setting	not happening in PLW
7.5	CCB health signal logic revised (Now will remain high) for penalty condition occurring with FC 108 due to wrong operation/not affecting operation/ Not a CCB Fault (i.e Both controllers selected as LEAD etc) The Brake electronic failure message will not generate on DDS	EL/3.2.19/3-phase (CCB), dtd 30.01.2023		Brake electronic failure message not generate on DDS
7.6	CCB health signal logic for FC 102 (In case of BC request from VCU is more than 90 %-above 9V DC) is changed i.e CCB health signal will not drop for FC 102 which will avoid loco detention/failure. The brake electronic failure message will not generate on DDS.		Could not performed by M/s Knorr	Presently Not happening in PLW
7.7	Booting time for CCB with TCAS/TPM/PTWS/DPWCS mode 15-20 sec. However, in case of absence of either one or both system booting time subsequently increased to 40-50 sec.			45 sec
8.0	Sanding Equipment			
8.1	Check Isolating Cock-134F is in open position. Press sander paddle Switch. (To confirm EP valves Operates)		Sand on Rail	Ok
9.0	Test Vigilance equipment : As per D&M test specification			Ok



39397

	Roof compnent Cab-1 & Cab-2								
S.NO.	DESCRIPTION	PL NO.	QPL/Nos.	SUPPLIER	Sr.No.	Warranty			
1	Pantograph	25880068	2	Contransys	14739-06/24, 14725-06/24				
2	Servo Motor	25880068	2	Contransys	14727-06/24,14739-06/24				
3	Air Intake Filter Assembly	29480103	2	SPECTRUM	O/C 71790/SFPL-0006/A/B, O/C 71790/SFPL-0008/A/B-MAY/2024				
4	Insulator Panto Mounting	29810127	8	MIL	12-2023, 01-2024				
			Middle root	f Component					
5	High Voltage Bushing	29731021	1	RADIANT	RE/06/05/24/HVB-05				
6	Voltage Transformer	2965028	1	SADTEM	2024-N-670211				
7	Vaccum Circuit Breaker	25712202	1	AUTOMETER	AALN/06/2024/056/VCBA/318				
8	8 Insulator Roof Line 29810139		9	BHEL	10-2023, 11-2023, 12-2023				
9	Harmonic Filter	29650033	1	ELECOS	EEPL/HF/1524	As per PO/IRS Conditions			
10	Earthing Switch	29700073	1	PPS	03/24/01032	·			
11	Surge Aresster	29750052	2	C G POWER	55108-2023, 55109-2023				
			Air Brake C	components					
12	Air Compressor (A,B)	29511008	2	ELGI	EXBS-922614 A EXBS-922606 B				
13	Air Dryer	29162051	1	TRIDENT	LD2-07-0424-24				
14	Auxillary Compressor	25513000	1	ELGI	BXBS 108924				
15	Air Brake Panel	29180016	1	KNORR	24-04-CO-3416				
16	Controller (A,B)	29180016	2	KNORR	24-06-FO-3625 A 24-06-FO-3625 B				
17	Break Up Valve	29162026	2	KNORR					
18	Wiper Motor		4	AUTO INDUSTRY					

SAMSHER Digitally signed by SAMSHER SINGH BIST Date: 2024.10.18 11:40:33 +05'30'

SSE/ABS

#### PLW/PTA

## **ELECTRIC LOCO HISTORY SHEET (ECS)**

ELECTRIC LOCO NO: 39397

**RLY: SWR** 

SHED: UBL PROPULSION SYSTEM: MEDHA

HOTEL LOAD CONVERTER: AAL

LIST OF ITEMS FITTED BY ECS

SN	DESCRIPTION OF ITEM	ITEM PL NO.	ITEM SR. NO CAB-1/CAB-2		MAKE/SUPPLIER
1	LED Based Flasher Light Cab I & II	29612937	4537	/4520	POWER TECH
2	Led Marker Light Cab I & II	29612925	142665/142785	/142657/142712	MATSUSHI P.T.
3	Cab Heater Cab I & II	29170011	2226	/2254	TOPGRIP
4	Crew Fan Cab I & II	29470080	5983/5991	/5989/6004	SARIA
5	Master Controller Cab I		69	20	WOAMA
6	Master Controller Cab II	29860015	69	23	VVOAIVIA
7	Complete Panel A Cab I & II	29170564	KT-1375	KT-1366	KONTACT
8	Complete Panel C Cab I & II	29170539	3139	3227	KEPCO/MEDHA
9	Complete Panel D Cab I & II	29170564	KT-1367	KT-1375	KONTACT
10	Complete Cubicle- F Panel Cab I & II	29178162			CG
11	Speed Ind & Rec. System	29200040	MTELS-24071	77/M-2407178	AAL
12	Battery (Ni- Cd)	29680025	5217	-5242	SAFT URJA
13	Set of Harnessed Cable Complete	29600418			PPS INTERNATIONAL
14	Transformer Oil Pressure Sensor (Cab-1) (pressure sensor oil circuit transformer)	29500047	TGIC/CLW/2938 & 05/24	TGIC/CLW/2924 & 05/24	TOPGRIP
15	Transformer Oil Pressure Sensor (Cab-2)		TGIC/CLW/2946 & 05/24	TGIC/CLW/2929 & 05/24	
16	Transformer Oil Temperature Sensor (Cab-1)(temperature sensor oil circuit transformer)	29500035	BG/TFP/5	709 Feb-24	BG INDUSTRIES
17	Transformer Oil Temperature Sensor (Cab-2)		BG/TFP/57	715 Feb-24	
18	Roof mounted Air Conditioner I	29811028	AE/CLW/262		AMIT ENGINEERING
19	Roof mounted Air Conditioner II	29011020	AE/CLW/265		AWIT LINGINGERING
			India rail navigator		
20.	RTIS(Real time information system)		Power supply module		Aventel Ltd., India
			Rail MSS Terminal		

SSE/ECS Jul

JE/ECS

		PATIALA LOCOMO	TIVE WORKS, PAT	IALA 🗸					
2.11	LOCO NO :- 39397/WAP-7/SWR/UBLD  N. Equipment PL No. Equipment Serial No. Make								
S.N.		PL No.			1 - 3 1 1	BHILAI			
	Complete Shell Assembly with piping	29171064		187 07/24	FASP	FASP			
	Side Buffer Assly Both Side Cab I	29130050	113, 07/24	187, 07/24	FASP	FASP			
-	Side Buffer Assly Both Side Cab II		104, 07/24	54, 07/24	ESCOR	ESCORTS			
	CBC Cab I & II	29130037	1272, 06/2024	1267, 06/2024		lodified Mechwel			
5	Hand Brake		U4/ Z4	4 - 17100	IVI	Jamea Wechwer			
6	Set of Secondry Helical Spring	29045034 29041041				GBD			
7	Battery Boxes (both side)	29680013	65, 06/24	70, 06/24	BRITE	BRITE METALLOY			
8	Traction Bar Bogie I		8637	7, 08/24		KM			
	Traction Bar Bogie II		8620	0, 08/24		KM			
	Centre Pivot Housing in Shell Bogie I side	20420057	HOU 1	71, 07/24		PEPL			
	Centre Pivot Housing in Shell Bogie II side	2910005/	HOU 1	154, 07/24		PEPL			
	Elastic Ring in Front in Shell Bogie I side			,12/23	A	SSPL			
-	Elastic Ring in Front in Shell Bogie II side	29100010		,12/23		SSPL			
	Main Transformer	29731008 for WAG 9 29731057 for WAP-7	CG-77-04-24-BH	HL11462/11, 2024		CG			
15	Oil Cooling Radiator I	*	0000	RPL, 05/24	STA	ANDARD RADIATORS			
	Oil Cooling Radiator I	29470031		RPL ,04/24		ANDARD RADIATORS			
-	Main Compressor I with Motor			2606, 05/24		ELGi			
-		29511008		2614, 05/24		ELGi			
-	Main Compressor II with Motor			1, 05/24	1	SAMAL HARAND			
-	Transformer Oil Cooling Pump I			6, 05/24	SAMAL HARAND				
-	Transformer Oil Cooling Pump II					D STEELS PVT LTD			
	Oil Cooling Blower OCB I	29470043		017, LHP1001512908		D STEELS PVT LTD			
	Oil Cooling Blower OCB II			020, LHP1001512912		ELECTRICAL PVT LTD			
	TM Blower I	29440075		2AF26, 24P0942/26		ELECTRICAL PVT LTD			
-	TM Blower II			1AF05, 24P1401/05	SAIIVI				
-	Machine Room Blower I	29440105		06, CGLXCAM11053		ACCEL			
-	Machine Room Blower II	25410111		01, CGLXCAM11044	1	ACCEL			
-	Machine Room Scavenging Blower I	29440129		M-24.05.59		G.T.R CO(P) LTD			
-	Machine Room Scavenging Blower II	23440125		6M-24.05.45		G.T.R CO(P) LTD			
-	TM Scavenging Blower Motor I	20440117		763, CF30/D8038		AL HARAND PVT LTD			
-	TM Scavenging Blower Motor II	29440117	07/24, D30-7	753, CF30/D8028	SAM/	AL HARAND PVT LTD			
-	Traction Convertor I		05/2	24, 5508					
-	Traction Convertor II		5507	7, 05/24					
-		20741075	3811	1, 05/24		MEDHA			
-		29741075	3811	1, 05/24					
				0, 05/24					
_				0, 05/24		001			
37	Axillary Control Cubical HB-1	29176645		1/24060037		CGL			
38	Axillary Control Cubical HB-2	29176657		0012407176		STESALIT LTD  CGL			
	·	29176669		1/24050704	TR	OLEX INDIA PVT LTD			
		29178174		605, 06/24		IND RECTIFIERS LTD			
	Filter Cubical (FB) (COMPLETE FILTER	29480140		/F/0656/563 07/24-39, 49, 52, 56	1	ABI			
L		29171131		07/24-39, 49, 52, 56 0037, 05/24	AUTOM	ETERS ALLAINCE PVT LTD			
-		29741087		0037, 05/24		ETERS ALLAINCE PVT LTD			
		29230044		SAL PIPES					
-		232300	0524020	0037, 05/24	AUTOM'	ETERS ALLAINCE PVT LTE			
47	Hotel Load Contactor II		0524020	0038, 05/24		ETERS ALLAINCE PVT LTD			
48	Conservator Tank Breather Silica Gel	29731057		37, 24-0273	YOG	SYA ENETRPRISES LTD			
49	Ballast Assembly ( only for WAG-9)	29170163			1.1	Dalat SQ			
50	Head Light	29611908	1005,			SUSHI POWER			
51	IV COUPLER			2,11440/21,11440/39	5.1141	TERNATIONAL PYT LTD			
	10/		1000			-			

NAME SHURMAM SHAFMA

NAME Karan Singh JE/LAS/

NAME ALLIT COPPER
JE/LAS/UF

Issue No. : 05 Effective Date: July-2023

DOC NO: F/LAS/Electric Loco CHECK SHEET (Ref: WI/LAS/Elect/01, 02, 03 & 04 & QPL/LAS/Elect. Loco)

## Page 1 of 1

#### पटियाला रेलइंजन कारखाना, पटियाला PATIALA LOCOMOTIVE WORKS, PATIALA ELECTRIC LOCO CHECK SHEET

LOCO NO: 39397

Rly: SWP

Shed: UBID

S. No.	ITEM TO BE CHECKED	Specified Value	0	bserved	Value	
1.1	Check proper Fitment of Hotel Load Converter & its output contactor.	OK		412		
1.2	Check proper Fitment of MR Blower 1 & 2, MR Scavenging Blower 1 & 2, TM Blower 1 & 2, TMB Scavenging Blower 1 & 2.  TM scavenging blower 1 & 2 & Oil Cooling unit.	OK		014		-
1.3	Check proper of Fitment of oil cooling unit (OCU).	OK		CLL		
1.4	Check proper Fitment of HB 1 & 2 and its respected lower part on its position.	OK	•	CIL		
1.5	Check proper Fitment of FB panel on its position.	OK		UL		
1.6	Check proper Fitment of assembled SB1 & SB2 panel.	OK		OL.		
1.7	Check proper Fitment of Auxiliary converter 1, 2 & 3-(BUR-1, 2 & 3).	OK		014		To past ou
1.8	Check proper Fitment of Traction converter 1 & 2 (SR-1 & 2).	OK		CIL		
1.9	Check proper fitment, torquing & Locking of Main Transformer bolt.	OK		UL		
10	Check proper fitment of Main compressor both side with the compressor safety wire rope.	OK -		CK		
1.11	Check proper resting of Secondary Helical Springs between Bogie & Shell body.	OK		UL		
1:12	Check proper fitment of Bogie Body Safety Chains.	OK		UL		
1.13	Check proper fitment of Cow catcher.	OK		OLL		
1.14	Check coolant level in SR 1 & 2 Expansion Tank.	- OK		UL	N.	
4.15	Check Transformer Oil Level in both conservators Tank (Breather Tank).	OK		CIL		
1.16	Check proper fitment and maintain required gaps from Loco Shell Body of all metallic pipes to avoid any damage during online working of Locomotives.	OK	636	UL		
1.17	Check proper fitment of both battery box.	OK		CL		(confidence)
1.18	Check for any gap between Main Transformer mounting base & Loco Shell.	OK		UL		
1.19	Check proper fitment of Push Pull rod its bolt torquing and fitment of fixing cable. As per Drg No 1209-01-113-001	OK		.OZ		
1.20	Secondary Vertical and Lateral Clearance on leveled track at the time of Loco Dispatch.		CAI	3-1	CAB-	2
	ELRS/TC/ 0082 (Rev 1) dated 17,09.2015	Vertical-Std	LP	ALP	LP A	ALP
		:35-60 mm			7 7 7	
						11
1.21	Differ height. Day (1900) 145 F)	Lateral Std- 45-50-mm	44		,,	42
1.21	Buffer height: Range (1090, +15,-5) Drg No IB031-02002.	1085-1105	1	L/S	R	RIS
	DIG NO 15031-02002.	mm _	FRONT	1096	10	95
Y			REAR	1096		98
1.22	Buffer Length: Range (641 mm + 3 to 10 mm with buffer face)	641 mm	-	L/S	R	RVS
	Drg No-SK.DL-3430.		FRONT	651	60	18
			REAR	645		44
1.23	Height of Rail Guard. (114 mm + 5 mm,-12 mm).	114 mm + 5		L/S	V	RVS
	As per RDSO Pamphlet Important Bogie Clearances of Electric Locomotives.	mm,-12 mm	FRONT	114		15
		in the second second	REAR	113		15
1.24	CBC Height: Range (1090, +15,-5)	1090, +15	FRONT:	1096		-
	Drg No- IB031-02002.	-5 mm	REAR:	1097	-	

(Signature of SSE/Elect. Loco)

NAME December feet for

DATE 28/08/24

(Signature of JOE/Elect Loco)

NAME SHUBHAM JHA RMA

DATE 28/08/24

(Signature of JE/UF)

DATE 28 08/24

#### 1. BOGIE FRAME:

BOGIE	FRAME NO	Make	PL No.	PO No. & dt.	Warranty Period
FRONT	SL-2313	ACPL	29101104	102222	As per PO/IRS
REAR	SL-2307	ACPL	29101104	102222	conditions

## 2. Hydraulic Dampers (PL No.29040140 ) Make: KONI/KONI

#### 3. AXLES:

AXLE POSITION NO	1	2	3	4	5	6
MAKE/	PLW	PLW	PLW	PLW	PLW	PLW
S.NO	26513	27058	26958	27311	26912	26750
Ultrasonic Testing	OK	OK	OK	OK	OK	OK

#### 4. WHEEL DISCS NO. AND TYPE & BULL GEAR

AXLE POSITION NO	1	2	3	4	5	6
GEAR END	22451	22546	22968	22839	20171	22515
Make	DP	DP	DP	IMPORTED	DP	DP
FREE END	23768	23344	23389	22752	23924	22834
Make	DP	DP	DP	DP	DP	DP
Bull Gear No.	23-M-1082	24-A-1671	23-M-983	24-A-1051	24-A-1664	24-A-1093
Bull Gear Make	KPCL	KPCL	KPCL	KPCL	KPCL	KPCL

## 5. AXLE ROLLER BEARING (CRU) (PL No. 29010020, Warranty: As per PO/IRS conditions)

	AXLE POSITION NO	1	2	3	4	5	6
Gear	MAKE	NBC	NBC	NBC	NBC	NBC	NBC
End	PO NO. & dt	02875	02875	02875	02875	02875	02875
Free	MAKE	NBC	NBC	NBC	NBC	NBC	NBC
End	PO NO. & dt	02875	02875	02875	02875	02875	02875

# 6. WHEEL DISC PRESSING PRESSURE IN KN: (SPECIFIED 80-105 T)

AXLE POSITION NO	1	2	3	4	5	6
BULL GEAR END	983 KN	983 KN	839 KN	922 KN	844 KN	811 KN
FREE END	892 KN	1010 KN	795 KN	887 KN	870 KN	831 KN

#### 7. DIAMETER AFTER PROFILE TURNING: SPECIFIED 1092 + 5 mm - 0 mm

AXLE POSITION NO	1	2	3	4	5	6
DIA IN mm GE	1092.5	1092.5	1092.5	1092.5	1092.5	1092.5
DIA IN mm FE	1092.5	1092.5	1092.5	1092.5	1092.5	1092.5
WHEEL PROFILE GAUGE (1596±0.5mm)	OK	OK	OK	OK	OK	OK

#### 8. SUSPENSION TUBE & ITS TAPER ROLLER BEARING:

AXLE POSITION NO		1	2	3	4	5	6
S.T. PL 29100288	MAKE	IN	BSL	BSL	IN	IN	IN
GE Brg. PL 29030110	MAKE	NBC	NBC	NBC	NBC	NBC	NBC
FE Brg. PL 29030110	MAKE	NBC	NBC	NBC	NBC	NBC	NBC

#### 9. GEAR CASE (PL No. 29030018) & BACKLASH:

AXLE POSITION NO	1	2	3	4	5	6
MAKE	TACPL	TACPL	TACPL	TACPL	TACPL	TACPL
BACKLASH (0.254 – 0.458mm)	0.310	0.300	0.310	0.320	0.350	0.300

#### 10 A/BOX TO BOGIE FRAME LATERAL CLEARANCES (SPECIFIED 15.0 to 19.0mm):

AXLE POSITION NO	1	2	3	4	5	6
RIGHT SIDE	17.80	16.75	17.05	17.90	18.10	16.82
LEFT SIDE	15.40	16.18	15.60	18.22	18.05	18.82

#### 11. TRACTION MOTOR: (PL No.29942007, Warranty: As per PO/IRS conditions)

AXLE POSITION NO	MAKE	PO No. & date	S. NO.
1	TMS	-	PLW-2823
2	TMS	-	PLW-2819
3	TMS	-	PLW-2920
4	TMS	-	PLW-2824
5	TMS	-	PLW-2841
6	SAINI	100508	203332405

SSE/ Bogie Shop

## TOP 13 COSTLIEST ITEMS OF WAP-7 LOCO WITH WARRANTY CONDITIONS AS PER TENDERS

S No	PL No	DESCRIPTION	Warranty Period
1	29741075	IGBT BASED 3-PHASE DRIVE PROPULSION EQUIPMENT	60 months after commissioning or 72 months from date of supply whichever earlier as per special conditions given by CLW
2	29741087	2X500KVA IGBT Based Hotel Load Converter to CLW Specn. no. CLW/ES/3/IGBT/0490 aLT.D (REV.1) issued on December,2017	As per clause no. 3.1.6 of CLW SPECN. NO. CLW/ES/3/IGBT/0490 ALT.D REV.1 ISSUED ON DEC-2017. [60 months after commissioning or 72 months from date of supply whichever earlier]
3	29731057	MAIN TRANSFORMER 7775 KVA TYPE LOT 7500 FOR WAP7 3- PHASE ELECTRIC LOCOMOTIVE TO CLW SPECN NO.CLW/ES/3/0660/C	AS PER IRS CONDITIONS OF CONTRACT [i.e. 30 MONTHS FROM THE DATE OF SUPPLY OR 24 MONTHS FROM THE DATE OF COMMISSIONING, WHICHEVER IS EARLIER] WILL BE APPLICABLE.
4	29171064	COMPLETE SHELL ASSLY (PIPED & PAINTED) FOR WAP-7 LOCO TO CLW SPEC. NO. CLW/MS/3/152 ALT-8	AS PER IRS CONDITIONS-30 MONTHS FROM THE DATE OF SUPPLY OR 24 MONTHS FROM THE DATE OF COMMISSIONING, WHICHEVER IS EARLIER.
5	29600418	SET OF HARNESSED CABLE FOR 3-PHASE ELECTRIC LOCOMOTIVES TO CLW SPECN. NO. CLW/ES/03/646 ALT-NIL WITH DMW REQUIREMENT OF HARNESSED CABLE FOR WAP-7, ALT-A1 DATED 27/11/2018.	As per clause no.9 of CLW Specn. CLW/ES/3/0458 & Clause No.10 of CLW SpecnCLW/ES/3/0459. [18 months after commissioning or 20 months from date of supply for single core & 18 months after commissioning or 24 months from date of supply for multi core]

6	29180016	BRAKE CONTROL SYSTEM INCLUDING DRIVER'S VIGILANCE CONTROL DEVICE TO SET LIST NO.EL29180016.	As per specification no. CLW/MS/3/001 Alt. 16 i.e. the manufacturer is required to guarantee that the brakevalves/equipment work satisfactorily for a period of five (5) years after commissioning. Any equipment/part which failsduring the guarantee period shall be replaced free of cost by the manufacturer. The replaced components shallfurther be under warranty for five (5) years from the date of their fitment and should the replaced components proveunsatisfactory in service, they shall be replaced by modified and improved components by the supplier free of cost.
		COMPLETE ELLTED CUDICUE ALCANO MUTULALI	
7	29480140	COMPLETE FILTER CUBICLE ALONG WITH ALL EQUIPMENTS AND CABLING TO DRG./SPEC NO. [1] CLW/ES/3/0193 ALT-F OR LATEST AND CLW DRG. NO. 1209-15-143-004 ALT-10 AND PART DRG./SPEC NO AS PER ANNEXURE-A ATTACHED.	AS PER IRS CONDITIONS OF CONTRACT [i.e. 30 MONTHS FROM THE DATE OF SUPPLY OR 24 MONTHS FROM THE DATE OF COMMISSIONING, WHICHEVER IS EARLIER] WILL BE APPLICABLE.
8	29942007	3-PHASE ASYNCHRONOUS TRACTION MOTOR (RESISTANCE RING MECHANICALLY INTERLOCKED TO END PLATE DESIGN ROTOR, SCHEME-II), TYPE 6FRA-6068 FOR WAP-7 ELECTRIC LOCO WITHOUT ACTIVE SPEED SENSOR TO SPECIFICATION NO. 4TMS.096.081 ALT-2 AND STR NO. CLW/2008/3PHTM/STR/0001.	AS PER IRS CONDITIONS OF CONTRACT [i.e. 30 MONTHS FROM THE DATE OF SUPPLY OR 24 MONTHS FROM THE DATE OF COMMISSIONING, WHICHEVER IS EARLIER] WILL BE APPLICABLE.

9	29105146	Bogie Frame Complete for WAP-7 for 3 Phase Co Co Locomotive to CLW specification No. CLW/MS/3/Bogie/003 alt-1 and CLW Drg.No.1209.01.112-202 Alt-Nil	As per clause 16 of Spec.No.CLW/MS/3/Bogie/003 Alt-1. [60 months after commissioning or 72 months from date of supply]
10	29171192	COMPLETE AUXILIARY CUBICLE HB2 ALONG WITH ALL EQUIPMENTS AND CABLING TO CLW SPEC.NO.CLW/ES/3/0192 ALT-E OR LATEST FOR WAP7 LOCO WITH HOTEL LOAD WITH BARE CUBICLE AS PER CLW SPEC.NO.CLW/MS/3/155 ALT-NIL.	AS PER IRS CONDITIONS OF CONTRACT [i.e. 30 MONTHS FROM THE DATE OF SUPPLY OR 24 MONTHS FROM THE DATE OF COMMISSIONING, WHICHEVER IS EARLIER] WILL BE APPLICABLE.
11	29171210	COMPLETE CONTROL CUBICLE SB2 ALONG WITH ALL EQUIPMENTS AND CABLING (EXCLUDING CONTROL ELECTRONICS) TO CLW SPECN. NO. CLW/ES/3/0195/A ALT-H OR LATEST FOR WAP7 LOCO WITH HOTEL LOAD	AS PER IRS CONDITIONS OF CONTRACT [i.e. 30 MONTHS FROM THE DATE OF SUPPLY OR 24 MONTHS FROM THE DATE OF COMMISSIONING, WHICHEVER IS EARLIER] WILL BE APPLICABLE.
12	29171209	COMPLETE CONTROL CUBICLE SB1 (PUSH PULL SCHEME COMPLIANT) ALONG WITH ALL EQUIPMENTS AND CABLING (EXCLUDING CONTROL ELECTRONICS) TO CLW SPECN. NO. CLW/ES/3/0194 ALT-G OR LATEST FOR WAP7 LOCO WITH HOTEL LOAD	AS PER IRS CONDITIONS OF CONTRACT [i.e. 30 MONTHS FROM THE DATE OF SUPPLY OR 24 MONTHS FROM THE DATE OF COMMISSIONING, WHICHEVER IS EARLIER] WILL BE APPLICABLE.
13	29171180	COMPLETE AUXILIARY CUBICLE HB1 ALONG WITH ALL EQUIPMENTS AND CABLING TO CLW SPEC.NO.CLW/ES/3/0191 ALT-D OR LATEST FOR WAP7 LOCO WITH HOTEL LOAD WITH BARE CUBICLE AS PER CLW SPEC.NO.CLW/MS/3/155 ALT-NIL.	AS PER IRS CONDITIONS OF CONTRACT [i.e. 30 MONTHS FROM THE DATE OF SUPPLY OR 24 MONTHS FROM THE DATE OF COMMISSIONING, WHICHEVER IS EARLIER] WILL BE APPLICABLE.



#### भारत सरकार **GOVERNMENT OF INDIA**

रेल मंत्राल्य

**MINISTRY OF RAILWAYS** 

पटियाला रेलइंजन कारखाना PATIALA LOCOMOTIVE WORKS फोन/ Phone: 0175- 2396422 मोबाईल: 9779242310 पटियाला, 147003, भारत PATIALA, 147003, INDIA

Email: dyceeloco.dmw@gmail.com

फैक्स/Fax No.: 0175-2397244

Date: 13.11.2024

(An ISO 9001, ISO 14001, ISO 45001 & ISO 50001, 5S & Green Building certified Organization)

No. PLW/M/ECS/Tech/Kayach

(Through Mail)

Sr. Div. Mechanical Engineer, Diesel Loco Shed, Hubli.

Email: srdmeubl@gmail.com

विषय:- Fitment of KAVACH in three Phase Electric Loco. No. 39397 WAP-7.

संदर्भ:- (i) Director General Stds./Electrical/RDSO letter no. EL/0.1.3/3 dated 21.08.2023.

(ii) Director General Stds./Electrical/RDSO letter no. EL/0.1.3/3 dated 26.09.2023

In ref. to the above letter's Loco No. 39397 has been dispatched with fittings for implementation of KAVACH system in locomotive at home shed in Zonal Railway. This Loco was dispatched to DLS/UBL/SWR on 27.09.2024. The details of fittings are attached as Annexure-A (pneumatic fittings), Annexure-B (Kavach equipment mounting Brackets) & Annexure-C (Wago with harnessed lay out).

This is for your information & necessary action please.

उप मुख्य विद्युत अभियंता/लोको

CEE/Loco & CEE/D&Q, CMM, CELE/SWR:- for kind information please Dy CME/Design, Dy. CMM/Depot: for information & necessary action please WM/LAS, AWM/LFS&ABS, WM/ECS: for necessary action please

List of balance items of KAVACH pneumatic pipes & fitting yet to be supplied later on. These items are currently under procurement process at PLW. The same will be advised to the shed for collection of the material as soon as it will be received at PLW.

SN	PL No.	Description of item .	Cty.
		ISOLATING COCK 3/8" (FEMALE) LEGRIS TYPE WITH VENT	04 nos.
.1	29163341	ISOLATING COCK 3/8" (FEMALE) LEGRIS TYPE WITHOUT VENT	02 nos.
		TEE UNION 3/8"X3/8"X3/8" BRASS FITTINGS	02 nos.
		MALE CONNECTORS 3/8" TUBE OD X 3/8" BSPT, BRASS FITTINGS	09 nos.
		MALE CONNECTORS 1/2" TUBE OD X 1/2" BSPT, BRASS FITTINGS	06 nos.
		FEMALE CONNECTORS (NYLON TUBE) DIA 6 TUBE X 3/8" BSPP BRASS FITTINGS	01 no.
		MALE CONNECTOR (NYLON TUBE) DIA 6 TUBE X 3/8" BSPP . BRASS FITTINGS	03 nos.
2	29611994	FEMALE TEE 3/8" BSPP – BRASS	06 nos.
		HEX PLUG -3/8" BSPT – BRASS	02 nos.
		FEMALE TEE 1/2" BSPP – BRASS	04 nos.
		HEX NIPPLE 3/8X3/8" BSPT – BRASS	04 nos.
		RED HEX NIPPLE 3/8X1/2" BSPT - BRASS	02 nos.
		HEX PLUG – 1/2" BSPT – BRASS	Q4 nos.
		MALE ELBOW CONNECTORS 3/8" TUBE ÓD X 3/8) BSPT. BRASS FITTINGS	02 nos.
3	29170114	Copper Tube OD 9.52mm (3/8") X 1.245 Mm W.T X 6 Mtr	1.2 Mtr

AWM/ABSTOTO9 MY

SSE /ABS/G

Annexure-B

SN	PL No.	Description of item	Quantity
1.	29611945	Mounting bracket arrangement provided for RF Antenna on the roof top of both driver cabs.	04 nos.
2.		Mounting bracket arrangement provided for GPS/GSM Antenna on the roof top of both driver cabs.	02 nos.
3.	· -	Protection Guards for RFID reader provided behind the cattle guards of both side.	04 nos.
4.	4	Inspection door with latch provided on the both driver desk covers (LP side) in each cab to access isolation cock.	02 nos.
5.		Cable Entry Plate fitted for routing of cable with RF Antenna & GPS/GSM Antenna bracket.	06 nos.
6.	· ·	WAGO bracket fitted in Machine room at back side of SB-1.	01 no.
7.	- 1	One circular hole of 80 mm dia. provided in each cabs on LP side behind the driver desk toward the wall for routing of OCIP (DMI) cables.	02 nos.
8.	-	80 mm holes provided on TM1 and TM6 Junction box inspection cover hole for drawing of RFID reader cables.	02 nos.
9.	-	DIN Rail fitted inside the driver desk (LP Side)	02 nos.

AWM/LFS

SSE/G/LFS

Annexure-C

SN	PL No.	Description of item	Quantity
1.	42310301	Flexible conduit size 25mm <sup>2</sup> provided for RF-1, 2 & GPS Antenna cable layout from CAB-1&2 to Machine room.	06 nos.
2.	29611982	Wago terminals in CAB-1&2 (25 nos. in each CAB).	50 nos.
3.	29611982	Wago terminal in Machine room at back side of SB-1.	75 nos.
4.	- '	Harness provided from KAVACH SB to SB-1	05 wires
5.		Harness provided from KAVACH SB to SB-2	05 wires
6.	-	Harness provided from KAVACH SB to Pneumatic Panel	12 wires
7.	-	Harness provided from KAVACH SB to CAB-1	24 wires
8.	-	Harness provided from KAVACH SB to CAB-2	16 wires

AVIMVECS

SSE/G/ECS